

Submit 3 Copies

To Appropriate

District Office

DISTRICT I

PO Box 1980, Hobbs, NM 88241-1980

DISTRICT II

PO Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

State of New Mexico
Energy, Minerals and Natural Resources Department

Form O-103

Revised 1-1-89

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO 30-025-11397
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-2317
7. Lease Name or Unit Agreement Name M.E. Hale
8. Well No. 1
9. Pool name or Wildcat Langie Matrix 7Rivers-Queen-Grayburg

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FCRM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well OIL <input type="checkbox"/> GAS <input type="checkbox"/> WELL <input checked="" type="checkbox"/> WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator Primal Energy Corporation	
3. Address of Operator 211 Highland Cross, Suite #227, Houston, TX 77073	
4. Well Location Unit Letter <u>G</u> <u>2310</u> Feet From The <u>N</u> Line and <u>2310</u> Feet From The <u>E</u> Line Section <u>2</u> Township <u>25S</u> Range <u>37E</u> NMPM <u>Lea</u> County <u></u> 10 Elevation (Show whether DF, RKB, PT, GR, etc.) 3166'DF	

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS ☐ PLUG & ABANDONMENT ☐
CASING TEST & CEMENT JOB ☐
OTHER ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed

work): SEE RULE 1103

1st Revision per Gary Wink

1. Set CIBP at 3075. Spot 25 sxs. Cement on top. Load hole w/9.5 ppg mud.
2. Spot 25 sx. From: 1170 to 1070'. Tag plug.
3. Spot 10 sx plug from 60' to surface. Erect marker and clean location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief

SIGNATURE 

TITLE Manager, Operations and Engineering

DATE 12/3/01

TYPE OR PRINT NAME John Abernethy

TELEPHONE NO. 281-871-5600

(This space for State Use)

APPROVED BY _____

TITLE _____

DATE 12/3/01

CONDITIONS OF APPROVAL IF ANY