

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-101  
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
7. Unit Agreement Name
8. Farm or Lease Name State NJ "A"
9. Well No. 2
10. Field and Pool, or Wildcat Undesignated
12. County Lea

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT - A" (FORM C-101) FOR SUCH PROPOSALS.)

1. ON WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Gas Storage
2. Name of Operator Amerada Hess Corporation
3. Address of Operator Drawer "D", Monument, New Mexico 88265
4. Location of Well UNIT LETTER A 592.3 FEET FROM THE North LINE AND 590.6 FEET FROM THE East LINE, SECTION 2 TOWNSHIP 25-S RANGE 37-E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.)

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
DRILL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well Temporarily Abandoned 1-17-62.

Well converted to a gas storage well for gas lift purposes by setting 10-3/4" cast iron bridge plug at 1905'. Installed casing head flange with outlet valves. Gas stored in casing only with no gas going to any outside formations. Top of cement in 10-3/4" casing is at 1933'.

PLAN TO: Load casing with mud, weld plate on 13-3/8" & 16" casing, install 4" x 4' dry hole marker. P&A.

100' plug @ Top Golt inside 10 3/4"  
10 5x5 plug @ top

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE SUPVR., ADM. SERV. DATE OCT 7 1972

APPROVED BY Joe D. Ramey DATE OCT 16 1972  
CONDITIONS OF APPROVAL, IF ANY: Dist. I, Supv.