

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.
B-11302

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT TO DRILL" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Unit Agreement Name
2. Name of Operator EXXON CORPORATION	8. Farm or Lease Name NEW MEXICO RM STATE
3. Address of Operator P.O. Box 1600, MIDLAND, TEXAS 79701	9. Well No. 1
4. Location of Well UNIT LETTER <u>I</u> <u>2310</u> FEET FROM THE <u>SOUTH</u> LINE AND <u>330</u> FEET FROM THE <u>EAST</u> LINE, SECTION <u>2</u> TOWNSHIP <u>25-S</u> RANGE <u>37-E</u> NMPM.	10. Field and Pool, or Wildcat JUSTIS FUSSELLMAN NORTH
11. Elevation (Show whether DF, RT, GR, etc.) 3138 RT	12. County LEA

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☒	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

PULL RODS, PUMP AND TBC OUT OF 4 1/2 CSG. PUMP CEMENT PLUG DOWN 4 1/2 CSG ACROSS PERFS. AND 100' ABOVE 6950-6845 W/155 SK. ESTABLISH FREE POINT AND CUT 4 1/2 CSG 4325. PULL 4 1/2 CSG. PUMP CEMENT PLUG DOWN 2 7/8 CSG. ACROSS PERFS. 100' ABOVE 6990-6824 W/105 SK. ESTABLISH FREE POINT AND CUT 2 7/8 CSG. 4325. SPOT 100' CMT. PLUG THROUGH 2 7/8 CSG. ACROSS AND ABOVE 4 1/2. 2 7/8 CSG CUTS W/45 SK., ACROSS 9 5/8 CSG. SHADE 3420-3520 W/45 SK. PULL 2 7/8 CSG. ESTABLISH FREE POINT AND PULL 9 5/8 CSG @ 2100'. RUN 2 7/8 TBC AND SPOT CEM. PLUGS, 100' PLUG ACROSS CSG. CUT 2050-2150 W/75 SK. 100' PLUG ACROSS TOP OF SALT SECTION 1020-1120 W/75 SK. 100' PLUG ACROSS 13 3/8" SURF. CSG. SHADE 186-286 W/75 SK. 10' PLUG AT SURFACE W/10 SK. PUMP ALL CEMENT PLUGS DOWN W/CELLED MUD. TAG ALL PLUGS W/CSG OR TBC. STRING TO VERIFY PLACEMENT. INSTALL MARKER AND CLEAN UP WELL SITE.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE UNIT HEAD DATE 6-5-74

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL IF ANY: