

UNIT STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPPLICATE  
(Other instructions on  
reverse side)

Form approved.  
Budget Bureau No. 1004-0135  
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. UNIT AGREEMENT NAME Langlie-Jal Unit
2. NAME OF OPERATOR Union Texas Petroleum Corporation		8. FARM OR LEASE NAME
3. ADDRESS OF OPERATOR 4000 N. Big Spring, Suite 500, Midland, TX 79705		9. WELL NO. 64
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 660 FSL & 1980 FEL		10. FIELD AND POOL, OR WILDCAT Langlie-Mattix (Queen)
14. PERMIT NO. WFX-552		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec 5, 25S, 37E
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3251 GR		12. COUNTY OR PARISH 13. STATE

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF	PULL OR ALTER CASING
FRACTURE TREAT	MULTIPLE COMPLETION
SHOOT OR ACIDIZE	ABANDON*
REPAIR WELL	CHANGE PLANS
(Other)	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF	REPAIRING WELL
FRACTURE TREATMENT	ALTERING CASING
SHOOTING OR ACIDIZING	ABANDONMENT*
(Other) Convert to Injection	X

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

- 12-14-85 1. MIRU Service Unit, POH Prod Equip.  
2. WIH, tag fill at 3656' from surface.  
3. Drill out to 3680', tbg to 3680'  
12-15-85 4. Perforate 2 SPF; 3295-3639'.  
5. Set pkr at 3254'; acidize w/4000' gals HCL, 2000 psi.  
6. FL 250' from surface, swab 45 BW.  
12-17-85 7. Nipple up wellhead and place on inj; w/1879 BW on vacuum.

FOR RECORD

*Mid*  
JAN 13 1986

CARLSBAD, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED *Ken White* TITLE Reg. Permit Coordinator DATE 1-8-86  
(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

Subject to  
Like Approval  
by State

\*See Instructions on Reverse Side

RECEIVED

JAN 14 1986

O.C.D.  
HOBBES OFFICE