


**SCOUT REPORT
NEW MEXICO
OIL CONSERVATION COMMISSION**



Company Anderson - Prichard
 Farm Name Wells Well No. 3
 Land Classification Patented
 Sec. 5 Twp. 25-S Range 37-E County Lea
 Feet from Line: 660 N. S. E. 1980 W.
 Elevation _____ Method _____
 Contractor Herschback Scout _____
 Spudded 8-7-38 Completed 10-21- Initial Production _____
 Bond Status _____

Casing and Cementing Record

Size	Feet	Inches	Sax Cement
<u>9 5/8</u>	<u>1210</u>		<u>500</u>
<u>7</u>	<u>3376</u>		<u>300</u>
<u>2 1/2</u>	<u>3537</u>		

packed
3433
perforated

ACID RECORD

Gals.	Prod.	Date
<u>Natural</u>		
	Prod.	Date
Top Pay <u>3450</u>	Total Depth	

SHOOTING RECORD

No. of Quarts	Shot at	Feet
No. of Quarts	Shot at	Feet

Date		Date	
<u>8-2</u>	<u>C&D</u>		<u>13 M Gas</u>
<u>8-9</u>	<u>φ 35-S RR.</u>		
<u>AUG 13 1938</u>	<u>T.D. 1210 FWD</u>	<u>SEP 26 1938</u>	<u>T.D. 3567 L</u>
<u>AUG 23 1938</u>	<u>φ 2880 L</u>		<u>meaning they</u>
<u>AUG 30 1938</u>	<u>T.D. 3380 L</u>	<u>OCT 4 1938</u>	<u>T.D. 3567 L</u>
	<u>Prep to run 7"</u>		<u>meaning they</u>
<u>SEP 7 - 1938</u>	<u>T.D. 3413 S</u>	<u>OCT 11 1938</u>	<u>T.D. 3567 L</u>
	<u>Gauging Gas</u>		<u>Packer Ratchet</u>
	<u>1/4 3410-135</u>		<u>To remove tubing</u>
	<u>Gauged 4,300 MI</u>		
<u>SEP 12 1938</u>	<u>T.D. 3567 L</u>	<u>OCT 18 1938</u>	<u>T.D. 3567 L</u>
	<u>Test.</u>		
	<u>Gas 9,240 MCF</u>	<u>OCT 25 1938</u>	<u>SI WO PL</u>
	<u>@ 3413 S</u>		<u>T.D. 3567 L</u>
<u>SEP 19 1938</u>	<u>T.D. 3567 L</u>		<u>1 P. 216 BORD.</u>
	<u>Prep to Run + 6g</u>		<u>200 MI Gas</u>
	<u>7130 P# 6 hrs.</u>		<u>CO R. 426</u>

35

[illegible]