Form 9-331 (Feb. 1951)	8



## (SUBMIT IN TRIPLICATE)

## UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Land Office_	Las	Cruce	•
Lease No. O	55546	<u> </u>	
Unit ei	ella		

0-770 AO

	TENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
	TENTION TO CHANGE PLANS		1
	TENTION TO TEST WATER SHUT-OF		i 1
	TENTION TO RE-DRILL OR REPAIR	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1 1
	TENTION TO SHOOT OR ACIDIZE	[	i I
NOTICE OF IN	TENTION TO PULL OR ALTER CASIN	l il	
NOTICE OF IN	TENTION TO ABANDON WELL	1 <b>I</b>	1 1
	(INDICATE ABOVE B	Y CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)	
		May 31	, 19.57
		County or Subdivision)  [Kange]  [Kange	
(⅓ Sec.	and Sec. No.) (Tv	wp.) (Range) (Meridian)	
angl16-	-Matcix	Lea New Sexion	<u> </u>
		DETAILS OF WORK sands; show sizes, weights, and lengths of proposed casings; indicate moints, and all other important proposed work)	
ropose urface ement W	to drill to appr pipe, cement wit (/300 sax using 2 esignation of Op a-Trichard in fav	eands; show sizes, weights, and lengths of proposed casings; indicate moints, and all other important proposed work)  *Ox. 3600', Queens Pay. Set 300'  th 250 sax, Set 3600' 5 1/2" Sil	8 5/8m tring. ed by
ropose urface ement M OTE: nderson	to drill to appr pipe, cement wit (/300 sax using 2 esignation of Op -Trichard in fav arch 12, 1956, si	cands; show sizes, weights; and lengths of proposed casings; indicate moints, and all other important proposed work)  Tox. 3600', Queens Pay. Set 300' th 250 sax, Set 3600' 5 1/2" Sil Stage method.  Derator dated March 12, 1956 signator of R. Olsen. Sesignation of Sesignation	8 5/88 tring. ed by perator vor R. Olse
ropose urface ement M OTE: nderson lated Ma	to drill to appr pipe, cement wit (/300 sax using 2 lesignation of Op - richard in fav arch 12, 1956, si	ands; show sizes, weights, and lengths of proposed casings; indicate moints, and all other important proposed work)  rox. 3600', Queens Pay. Set 300' th 250 sax, Set 3600' 5 1/2" Silved Stage method.  Perator dated March 12, 1956 signator of R. Olsen. Sesignation of Signed by 1st. Chicago Corp. in far	8 5/88 tring. ed by perator vor R. Olse
ropose urface ement M OTE: nderson lated Ma	to drill to appr pipe, cessent wit (/300 sax using 2 lesignation of Op le-Trichard in fav arch 12, 1956, si	ands; show sizes, weights, and lengths of proposed casings; indicate moints, and all other important proposed work)  TOX. 3600', Queens Pay. Set 300' to 250 sax, Set 3600' 5 1/2" Silver Stage method.  Perstor dated March 12, 1956 signation of R. Olsen. Besignation of Signed by 1st. Chicago Sorp. in far greed by 1st. Chicago Sorp. in far in the superior of the second seco	8 5/88 tring. ed by perator vor R. Olse