

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
310 Old Santa Fe Trail, Room 206
Santa Fe, New Mexico 87503

WELL API NO. 30-025-11481
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. 8910115870
7. Lease Name or Unit Agreement Name Langlie Jal Unit
8. Well No. 32
9. Pool name or Wildcat Langlie Mattix

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator GP II Energy, Inc.	
3. Address of Operator P. O. Box 50682	
4. Well Location Unit Letter <u>C 1</u> : <u>660</u> Feet From The <u>North</u> Line and <u>1919.6</u> Feet From The <u>West</u> Line Section <u>6</u> Township <u>25 S</u> Range <u>37 E</u> NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

11-8-95 - 12-2-95

Add perms 3288'-3348'. Acidize perms. Squeeze perms.
Add perms 3032'-3270'. Acidize perms. Squeeze perms.
Drill out cmt with 4 3/4" bit on 6 3 1/2" DCs.
Clean out to top of open hole. Circ.
RU to drill w/air. Clean out to TD - 3490'.
Drill new 4 3/4" hole from 3490'-3425'.
Swab well. RTP.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE George P. Mitchell, II TITLE President DATE 12-3-95

TYPE OR PRINT NAME George P. Mitchell, II TELEPHONE NO. 915 684-4748

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

