	UNIT	STATES	CONS. Budget Bureau No. 1004-0135 Expires Garch 31, 1993 Stor Bestation and Serial No.
ne 1990)	DEPARTMENT	OF THE INTERIOR	CONS. Expires Garch 31, 1993
	BUREAU OF LA	ND MANAGEMENT N.M. O	980 5 COC Broghauon and Serial No.
	SUNDRY NOTICES A	ND REPORTS ON WELLS P.O. DC	NEW LC032511E
o not use this f	orm for proposals to drill Jse "APPLICATION FOR I	or to deepen or reentry to a different PERMIT—" for such proposals	reservoir.
	SUBMIT II	N TRIPLICATE	CONS. Budget Bureau No. 1004-0135 Expire a Garch 31, 1993 Stor Bestation and Serial No. NEW MLCO32511E 6. If Indian, Allottee or Tribe Name reservoir. 7. If Unit or CA, Agreement Designation
Type of Well		· · · · · · · · · · · · · · · · · · ·	8910115870
X Oil Well Gas Other Other			8. Well Name and No.
Name of Operator		Langlie Jal Unit #86 9. API Well No.	
GP II Energ	gy, Inc.	·	30-025-11500
		10. Field and Pool, or Exploratory Area	
Location of Well (Four	50682 Midla ge, Sec., T., R., M., or Survey Descr	Langlie Mattix (SRQ)	
0,430'FS	L & 2310' FEL		11. County or Parish, State
S 8, T 25S	. R 37E		. Lea County, N. M.
		TO INDICATE NATURE OF NOTIO	
2. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OF			
	SUBMISSION		
Notice	of Intent	Abandonment	Change of Plans
		Recompletion Plugging Back	New Construction
LA Subse	uent Report	Casing Repair	Water Shut-Off
	Abandonment Notice	Altering Casing	Conversion to Injection
		X Other Add perfs	Dispose Water (Note: Report results of multiple completion on Well
01-16-96 - 0		o' 3341'-45 3312'-13' 3300'-08', 328	2'-3290', 3265'-3270', 3255'-3260'.
Perf 3435'-3	8', 3399'-3401', 3357'-335 s.	y, 3541 -45, 3512 19, 3500 -00, 01	
••••	8', 3399'-3401', 3357'-335 s.	y, 5541 -45, 5512 (9, 5566 - 66, 516	
Perf 3435'-3 Acidize perfs	8', 3399'-3401', 3357'-335 s.		
Perf 3435'-3 Acidize perfs	8', 3399'-3401', 3357'-335 s.	, , , , , , , , , , , , , , , , , , , ,	
Perf 3435'-3 Acidize perfs	8', 3399'-3401', 3357'-335 s.	y, 5541 -45, 5512 19, 5566 - 66, 61	10
Perf 3435'-3 Acidize perfs	8', 3399'-3401', 3357'-335 s.	y, 5541 -45, 5512 (19, 5566 - 66, 566	JOms
Perf 3435'-3 Acidize perfs	8', 3399'-3401', 3357'-335 s.	y, 5541 -45, 5512 19, 5566 00, 526	JOmo
Perf 3435'-3 Acidize perfs RTP.	S.	y, 5541 -45, 5512 19, 5666 00, 66	JOms
Perf 3435'-3 Acidize perfs RTP. 4. 1 hereby certify the th Signed	e forceroing is true and correct		
Perf 3435'-3 Acidize perfs RTP.	e forceroing is true and correct		Date96
Perf 3435'-3 Acidize perfs RTP.	e forceroing is true and correct		JOms
Perf 3435'-3 Acidize perfs RTP. 4. 1 hereby certify that the Signed	e forceroing is true and correct	Title President	Date96
Perf 3435'-3 Acidize perfs RTP.	e forceroing is true and correct		Date1-19-96