

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-7

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

0+6-NMOC-D-Hobbs 1-Mr. J.A.-Midland
1-File 1-Laura Richardson-Midland
1-Engr. BDB
1-Foreman CK

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Unit Agreement Name S. Langlie Jal Unit
2. Name of Operator Getty Oil Company	8. Farm or Lease Name -
3. Address of Operator P.O. Box 730, Hobbs, N.M. 88240	9. Well No. 6
4. Location of Well UNIT LETTER <u>K</u> <u>2310</u> FEET FROM THE <u>south</u> LINE AND <u>2310</u> FEET FROM THE <u>west</u> LINE, SECTION <u>8</u> TOWNSHIP <u>25-S</u> RANGE <u>37-E</u> N.M.P.M.	10. Field and Pool, or Wildcat Jalmat Field
11. Elevation (Show whether DF, RT, GR, etc.) 3148' G.R.	12. County Lea

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☒	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Pull rods, install BOP, and pull 2 3/8" tbg. set @ 3498'.
2. TIH w/bit and scraper to TD 3540'.
3. Run GR-N log. Perforate the Jalmat 7-Rivers-Queen, 1 spf, at 3141', 43', 45', 47', 49', 51', 53', 71', 73', 3205', 21', 22', 70-72', 3336', 38', 40', 42', 44', 46', 48', 50', 52', 55', 66', 85', 96', 3420', 24', 3502-04', 12-14', 20', 28-30', total 40 holes.
4. Acidize all Jalmat 7-Rivers-Queen perms (79 holes) w/11,000 gals. 15% NEFE w/clay stabilizers and 120 ball sealers.
5. Set RBP @ 3388', pkr. @ 3050', and frac the upper 7-Rivers perms, 3141-3172' (19 holes, 40' net) w/31,000 gals. gelled water and CO₂, 10,000# 20/40 sand, 14,000# 10/20 sand, w/10 ball sealers, in 2 stages.
6. Retrieve RBP and TOH. TIH w/2 3/8" tbg. and pkr. and put well on pump.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED BDB John R. Crockett TITLE Area Superintendent DATE 2/29/84
ORIGINAL SIGNED BY JERRY SEXTON
APPROVED BY DISTRICT 1 SUPERVISOR TITLE _____ DATE MAR 13 1984
CONDITIONS OF APPROVAL, IF ANY: