

COPIES RECEIVED		
TRIBUTION		
FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State ☐ Patented Fee ☐
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- 2. Name of Operator Union Texas Petroleum Corporation 3. Address of Operator 1300 Wilco Bldg., Midland, Texas 79701 4. Location of Well UNIT LETTER C 660 FEET FROM THE North LINE AND 2310 FEET FROM THE West LINE, SECTION 8 TOWNSHIP 25-S RANGE 37-E NMPM. 15. Elevation (Show whether DF, RT, GR, etc.) 3190 RT	7. Unit Agreement Name Langlie-Jal Unit 8. Farm or Lease Name 9. Well No. 72 10. Field and Pool, or Wildcat Langlie-Mattix (Queen) 12. County Lea
--	---

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/> Clean Out & Deepen

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. RU and re-enter well.
2. Clean out to original TD 3476'.
3. Deepen well to 3725' and run logs. (4-3/4" hole).
4. Run 4" Liner.
5. Perforate well and acidize Seven-Rivers (Queen) formation.
6. Run tubing and rods.
7. Place well on production in Seven-Rivers (Queen) Formation.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Stanley A. Port TITLE Gas Meas. Analyst DATE 8-20-74

APPROVED BY Joe B. Namey TITLE Asst. Dir. DATE 8-21-1974
CONDITIONS OF APPROVAL, IF ANY: