

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

N.M. CONS. COMMISSION
P.O. BOX 1980
HOBBS NEW MEXICO 88240
Expires: March 31, 1993
LC 032511A

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well ☐ Oil Well ☐ Gas Well ☒ Other Injection	6. If Indian, Allottee or Tribe Name
2. Name of Operator GP II Energy, Inc.	7. If Unit or CA, Agreement Designation 8910115870
3. Address and Telephone No. P. O. Box 50682 Midland, Tx. 79710 915-684-4748	8. Well Name and No. Langlie Jal Unit #83
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) L, 1980' FSL & 660' FWL S 9, T 25S, R 37E	9. API Well No. 30-025-1151300
	10. Field and Pool, or Exploratory Area Langlie Mattix
	11. County or Parish, State Lea County, N. M.

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA		
TYPE OF SUBMISSION	TYPE OF ACTION	
☐ Notice of Intent	☐ Abandonment	☐ Change of Plans
☒ Subsequent Report	☐ Recompletion	☐ New Construction
☐ Final Abandonment Notice	☐ Plugging Back	☐ Non-Routine Fracturing
	☐ Casing Repair	☐ Water Shut-Off
	☐ Altering Casing	☐ Conversion to Injection
	☒ Other Deepen. Add perfs	☐ Dispose Water
		(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

03-11-96 - 04-04-96

MIRU PU. RIH w/bit & scraper. Drill out iron plug @ 2796'. Drill out hard cmt, hard scale & junk to 3125' New formation in returns. Drill to 3130'. Circ clean.

Drill new 4 3/4" hole from 3130' to 3649'. Circ. Run 4" liner to btm. Cmt w/70 sx.

RIH w/5 1/2" Watson squeeze pkr on 2 7/8" work string. Tag @ 1920'. Set pkr. Press test tbq to 1000#. Held okay.

Perf 3318'-28', 3332'-40', 3354'-58', 3365'-74', 3382'-88', 3392'-96', 3399'-3402', 3414'-20', 3426'-28', 3432'-34', 3444'-56', 3466'-72', 3486'-95', 3506'-14', 3520'-32', 3536'-38', 3548'-50', 3557'-60', 3568'-72', 3576'-78', 3584'-92', 3610'-22.

RIH w/AD-1 pkr & set @ 3263'.

Acidize perfs.

RIH w/Baker AD-1 tension pkr. Displace w/65 bbls pkr fluid. Set pkr w/14000# tension. Hook up wtr meter. PCI.

14. I hereby certify that the foregoing is true and correct

Signed [Signature] Title President

Date 4-5-96

(This space for Federal or State office use)

Approved by _____
Conditions of approval, if any:

Title _____ Date _____

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

*See Instruction on Reverse Side