NO. OF COPIES RECEIVED		
DISTRIBUTION	ļ	
SANTA FE	1	
FILE		ļ
U.S.G.S.		<u> </u>
LAND OFFICE		
	1	l

Form C-103 Supersedes Old C-102 and C-103

		これの私なら	OFFIRE D.C.C.C	er r		
SANTA FE	NEW MEXICO OIL CONSERVATION COMMISSIO	NHOBOO	O. Francisco	~ 0>		
FILE		i 1	Sa. Indicate TAS	of Lease		
U.S.G.S.		JUN	1 43 API 10	Fee, X		
LAND OFFICE			5, State Oil & Go			
OPERATOR			0, 2, 3, 3			
			mmm	mmm		
SUNE	DRY NOTICES AND REPORTS ON WELLS PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESER CATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	/01R.				
1.			7. Unit Agreeme	nt Name		
OIL X GAS WELL	OTHER-		8. Furm or Leas	e Name		
2. Name of Operator				_		
TEXAS PACIFIC CIL	, COPANY		9. Well No.	_aton b. b.		
3. Address of Operator			1 -7			
P. G. Box 1069 -	hobbs, New mexico		ř.) MI(1)		
4. Location of Well			10. Field and Pe			
.7	1650 FEET FROM THE CUTE LINE AND 201	FEET FR	om Tanglia	Mattix		
UNIT LETTER	FEET FROM THE					
East es	CTION 12 TOWNSHIP 25-S RANGE 37-	NMP	M. (((()))			
THECINE, 320			<u> </u>	<i>171111111</i>		
	15. Elevation (Show whether DF, RT, GR, etc.)		12, County			
	3091.81		Lea	<u> </u>		
16. Cl	k Appropriate Box To Indicate Nature of Notice. Ro	port or C	Other Data			
		IBSFOLE	NT REPORT OF	:		
NOTICE OF	FINTENTION TO:					
	PLUG AND ABANDON REMEDIAL WORK		ALTE	RING CASING		
PERFORM REMEDIAL WORK	COMMENCE DRILLING OPN	<u> </u>	PLUG	AND ABANDONMENT		
TEMPORARILY ABANDON						
PULL OR ALTER CASING						
	OTHER					
OTHER						
	d Operations (Clearly state all pertinent details, and give pertinent if	res, includ	ing estimated date of	f starting any propose		
17 Describe Proposed or Completed	d Operations (Clearly state all pertinent details, and give pertine.	,				
work) SEE RULE 1103.						

- Rig up. Pull rods, pump and tubing.
- Perf. w/1 3/8" shots 0 3100-16-44-50-88-3206-14-5'-50-70".
- Plug back to 3320 w/plaster sand.
- Acidize perfs. w/750 gals. 15% NE acid and flush.
- 5. Water frac perfs. w/20,000 gal. gelled brine + 15,000# 20/40 sd. and flush.
- 6. Run tubing and reverse out plaster sand to present PBTD 34291.

7. Run pump and rods, recover load	d and]	lace well on production a	and test.	
. I hereby certify that the information above is true and completed original Signed by	te to the b	est of my knowledge and belief.		
Sheldon Ward	TITLE	Area Superintondent	DATE	5 -31- 67
PROVED BY Line 1	T TLE		DATE	
ONDITIONS OF APPROVAL, IF ANY:				