

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

OIL CONSERVATION DIVISION

DISTRICT I  
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

2040 Pacheco St.  
Santa Fe, NM 87505

WELL API NO. 3002511547
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Eaton SW
8. Well No. 6
9. Pool name or Wildcat Langlie Mattox 7 Rvs Qn Grbg

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	2. Name of Operator Mack Energy Corporation
3. Address of Operator P.O. Box 960, Artesia, NM 88211	4. Well Location Unit Letter L : 1980 Feet From The South Line and 660 Feet From The West Line Section 12 Township 25S Range 37E NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER: <input type="checkbox"/>	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Will need to MIRU wellservice unit, pull production equipment.
2. MIRU plugging unit.
3. Spot 25 sx cmt. 3280-3180', WOC & tag.
4. Spot 25 sx cmt. 2395-2295'.
5. Spot 25 sx cmt. 1165-1065'.
6. Perforate 5-1/2" csg. @ 353', sqz w/ 40 sx 353-253', WOC & tag.
7. Spot 10 sx 60-3'.
8. RD, cut off wellhead, install dry hole marker, & clean location.

Verbal Approval From Gary Wink w/ NM OCD on 5-30-02

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Tony Hall TITLE Supervisor DATE 05/31/02  
TYPE OR PRINT NAME Tony Hall TELEPHONE NO. (505) 748-1288

(This space for State Use)

APPROVED BY GARY W. WINK TITLE Supervisor DATE 05/31/02  
CONDITIONS OF APPROVAL, IF ANY: