## UPTED STATES SUBMIT IN TRIP (Other Instruction Other Instruction verse side)

Form approved.
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.

G	SEOLOGICAL SURVEY	HOBBS OFFICE O	NM 0766
SUNDRY NOT  (Do not use this form for propos  Use "APPLICA"	ICES AND REPORTS ON tals to drill or to deepen or plug back	WELLS	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
1.			7. UNIT AGREEMENT NAME
OIL X WELL OTHER  2. NAME OF OPERATOR			8. FARM OR LEASE NAME
Union Texas Petroleum Corporation			Blocker
3. ADDRESS OF OPERATOR			9. WELL NO.
1300 Wilco Bldg., Midland, Texas			5
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*  See also space 17 below.)  At surface			10. FIELD AND POOL, OR WILDCAT JUSTIS
At suitace		•	11. SEC., T., R., M., OR BLK. AND
2310' FNL & 750' FWL			Sec 13, T-25-S, R-37
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT	, GR, etc.)	12. COUNTY OR PARISH 13. STATE
	3099 DF		Lea: New Mex.
16. Check Ap	propriate Box To Indicate Nat	ure of Notice, Report, or	Other Data
. NOTICE OF INTENTION TO:		EQUENT REPORT OF:	
TEST WATER SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL
FRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT	X ALTERING CASING
J <del></del>	ABANDON*	SHOOTING OR ACIDIZING	ABANDONMENT*
REPAIR WELL (Other)	CHANGE PLANS	(Other)(Note: Report resu	its of multiple completion on Well appletion Report and Log form.)
	RATIONS (Clearly state all pertinent denaily drilled, give subsurface location		es, including estimated date of starting any lical depths for all markers and sones perti-
Squeezed Tubb Drinkard	<del>-</del>	~	
Squeezed Blinebry perf	_		
Perforated Tubb Drinkard 5859-5965 w/15 holes. Fraced			w/20,000 gals. gel
brine plus 30,000# sand.			
Perforated Tubb Drinkard 5761-5844 w/10 holes. Fraced brine plus 10,000# sand.			w.io,000 gars. ger
Perforated Blinebry 55		Fraced w/10	000 gals gal bring
plus 11,720# sand.	JJ-JU47 W/20 HOICS	· Praced w/ro,	AND
			000 gals, gel brine
plus 30,000# sand.	• • • • • • • • • • • • • • • • • • • •		
			000 gals, brine plus
15,000 #  sand.			- 불편설닷컴 이 휴 시험률은
			000 gals gel brine
plus 15,000# sand.			
Set packer at 5696', r	an tubing and put (	on production.	of Survey to a control of the survey to a contro
18. I hereby certify that the foregoing is	<i></i>	_	
SIGNED Caref G. B	TITLE Off:	ice Supervisor	DATE 12-2-66

DEC 5 1956

TITLE

(This space for Federal or State office use)