Submit 3 Copies to Appropriate

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revisied 1-1-89

OIL CONSERVATION DIVISION

P.O. Box 2088 DISTRICT I P.O. Box 1980, Hobbs, NM 88240 DISTRICT II P.O. Drawer Dd, Artesia, NM 88210 DISTRICT III 1000 Rio Brazos Rd., Aztec, Nm 87410 Santa Fe, New Mexico 87504-2088 API NO. (assigned by OCD on New Wells) 30-025-11569 5. Indicate Type of Lease STATE FEE[X]
P.O. Box 1980, Hobbs, NM 88240 DISTRICT II P.O. Drawer Dd, Artesia, NM 88210 DISTRICT III API NO. (assigned by OCD on New Wells) 30-025-11569 5. Indicate Type of Lease
P. O. Drawer Dd, Artesia, NM 88210 DISTRICT III 5. Indicate Type of Lease
1000 Rio Brazos Rd. Aztec. Nm 87410
OTALL TEEK
6. State Oil & Gas Lease No. 041912
SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BAC 7. Lease Name or Unit Agreement Name DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.) Learcy McBuffington
1. Type of Well: OIL GAS
WELL X WELL OTHER
2. Name of Operator ARCH PETROLEUM INC. 8. Well No. 8
3. Address of Operator 10 DESTA DRIVE, SUITE 420E, MIDLAND, TX 79705 9. Pool name or Wildcat Justis Fusselman
4. Well Location
Section 13 Township 25S Range 37E NMPM LEA County
10. Elevation(Show whether DF, RKB, RT, GR, etc.) GL=3084'
11 Check Appropriate Box to Indecate Nature of Notice, Report, or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTER CASING
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABAN. PULL OR ALTER CASING CASING CASING TEST AND CMT JOB
OTHER: Acidize Existing Fusselman Perfs
 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.
4/11/06 4/11/06
4711130
MIRU workover unit. POH w/rods & tbg. RU wireline truck. Set CIBP @ 6624'.
RIH & set Lock-set pkr @ 6600'. Staddle perfs f/6609'-6611' & Acidize w/1,000 gal 15% NEFE HCL. Swab back load. POH w/tbg & pkr. RIH w/1 jt MA, 4' PS, 2-7/8" SN, 209 jts 2-7/8" tbg. NUBOP. NUWH.
RIH w/10' GA, 2X 1-1/2"X 24' pump, 111- 3/4", 75- 7/8", 75- 1", 1X 4', & 1X6'. HWO.
Started pumping well on 4-15-96.
I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNITURE CALLULE STATE: 5/13/96
TYPE OR PRINT NAME BOBBIE BROOKS TELEPHONE NO. 915/685-1961
APPROVED BY ORIGINAL SIGNED BY TITLE DATE MAY 15 1996
CONDITIONS OF APPROVAL, ICANARY WHEN