NO. OF COPIES RECEIVED	<i>[</i> ≫−	
DISTRIBUTION	*	Supersedes Old C-102 and C-103
SANTA FE	NEW MEXICO OIL CONSERVATION COMMIS	
FILE	Orig & 3cc: NMOCC	
U.S.G.S.	co: File	5a. Indicate Type of Lease
LAND OFFICE		State Free X
OPERATOR	Orig & 3cc: NMOCC cc: File	Solution Cil & Das Lease No.
(DO NOT USE THIS FORM FOR PRO USE "APPLICATI	Y NOTICES AND REPORTS ON WELLS posals to drill or to deepen or plug back to a different re- ion for permit	
		7, Unit Agreement Name
WELL WELL	OTHER. Dual Oil - Water Injection We	ell.
2. Name of Operator		
	y Oil Company	Justis McKee Unit
3. Address of Operator	. Box 249, Hobbs, New Mexico	
	612	
4. Location of Well	10, iffeld and isoch, or Willoat	
UNIT LETTER I	650 FEET FROM THE South LINE AND 990	FEET FROM Justis Blinebry McKee
THE <b>East</b> LINE, SECTION	DN 13 TOWNSHIP 258 RANGE 37E	
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	3088 DF	Lea
<sup>16.</sup> Check	Appropriate Box To Indicate Nature of Notice,	Report or Other Data
		SUBSEQUENT REPORT OF:
PERFORM F TEMPORAR PULL OR A	COMMENCE DESLEMENT	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any over edwork) SEE RULE 1103.

Pulled rods and tubing on Blinebry zone. Pulled McKee tubing and packer. No evidence of outside corrosion on McKee tubing and packer appeared CK. Tested McKee tubing in hole w/4500#. Found few slight collar drips, but no major leaks. Ran 4-1/2" retrievable BP and 7" packer. Set BP at 7608 and packer at 6991. Pumped in 2 BPM at 750#. Set BP at 7217 and packer at 6600. Pumped in 2 BPM at 750#. Set BP at 7057 and packer at 6440. Pumped 20 BW at 2 BPM at 1000#. ISIP 600#, two minutes vacuum. Set BP at 7195 and dumped two sacks frac sand on top. Tagged sand at 7184. Pulled packer and removed tail pipe. Set packer at 6920, squeezed w/50 sacks regular cement w/2# salt/sack and CFR-2. Ran 6-1/4" bit and tagged top of cement at 6988. Drilled cmt from 6988 to top of liner at 7054. Ran 3-7/8" bit and drilled hard cement from 7054 (top of liner) to 7058. Drilled stringers to 7083. Set packer at 7046 and tested at 2000# for 30 minutes, CK. Pulled 7" packer and recovered bridge plug. Ran #1 string internally plastic coated McKee tubing. Spotted inhibited water on back side from 4-1/2" packer back to bottom of Blinebry perforations. Set packer at 7580 and tubing at 7646. Tubing tested in hole w/4500#.

	certify that the information above is true and co	implete to the best	of my knowledge and belief.	
	Original Signed By C. L. WADE		Area Sunt	10-10-67
SIGNED		TITLE	Area Supt.	
APPROVED BY	5 OF APPROVAL HE ANY:	TITLE		DATE