Form 3160-5	UNITED	states 1625 N. Fre	nah Briva
(JUNE 1990)	DEPARTMENT OF T	H TERIOR Hobbs, NM	Dudger Duteau 140. 1004-0155
	BUREAU OF LAND MANAGEMENT		Expires: March 31, 1993
			5. Lease Designation and Serial No.
SUNDRY NOTICES AND REPORTS ON WELLS			SW 17- N.M. 0766
Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.			6. If Indian, Allottee or Tribe Name
<u></u>	Use "APPLICATION FOR	PERMIT" for such proposals	
	SUBMIT II	N TRIPLICATE	7. If Unit or CA, Agreement Designation
1. Type of We			8. Well Name and No.
Oil Veil Other			Carlson Federal # 1 9. API Well No.
2. Name of Ope			
Gruy Petroleum Management Co. 3. Address and Telephone No.			30-025-11574 10. Field and Pool, or Exploratory Area
5. Audiess and	Telephone No.	To. Field and Fool, of Exploratory Alex	
600 E. Las Colinas Blvd. Irviing, Tx., 75039, 972-401-3111			Justis Glorietta
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			11. County or Parish, State
1650'FNL & 1650' FWL, Sec. 13, Twp. 25S, Rge. 37 E.			Lea, N.M.
12		X (s) TO INDICATE NATURE OF NOTICE, I	
	E OF SUBMISSION	TYPE OF A	
	Notice of Intent	Abandonment	Change of Plans
		Recompletion	New Construction
	Subsequent Report	Plugging Back	Non-Routine Fracturing
		Casing Repair	Water Shut-Off
	Final Abandonment Notice	Altering Casing	Conversion to Injection
		Other	Dispose Water
			(Note: Report results of multiple completion on Well Completion or Recompletion Report and log form)
	oposed or Completed Operations (Clearly state all po ace locations and measured and true vertical depths f	ertinent details, and give pertinent dates, including estimated date of starti or all markers and zones pertinent to this work.)*	ng any proposed work. If wells directionally drilled,
7/27/99,	TIH and tag TOC @ 4601', Circ	ulate Csg. With 10 ppg. Mud, (25 # of gel pe	er BBL.)
		ment 10 sks., Pump fresh water spacer, pun	
Pull Tbg. To 1253', break circ with mud, pump fresh water spacer, pump 10 sks cement, pump fresh water spacer, mud to balance. SD plug on spot. Cal TOC 1106'. Did not tag plug, Repeat plug at 1253' with 30 sks P+2% cacl2.			
Break circ with mud, pump fresh spacer, mix and pump 15 sks cement, fresh water spacer, mud plug to balance.			
POOH with Tbg. Cal. TOC 721', Shut down for day.			
7/28/99,	RIH tag		
	-	with Tbg. To 846', pump cement to Surface,	circ. 16 bbls Cement.
	th Tbg., Hose in cement to surfa		
7/29/99 Cut off surface pipe, weld plate over 4 1/2"Csg. Install 4" Dry Hole marker. Job wittnessed by Marlan Deaton (BLM).			
PETER W. C			PVED
		AUG 1 9	1999
			1
14. I hereby of	certify that the foregoing is true and correct	BUREAU OF LAND A ROSWELL RESOU	AANAGEMENT
Signed	Korld H	Title Production Supervisor	Date 2-Aug-99
(This space	for Federal or State office use)		
Approved by		Title	Date
	f approval, if any:		Date
	Section ((0)) makes it a crime for any nerson known	ngly and willfully to make to any department or agency of the United State	es any talse, licitious or braudulent statements
or representation	section foot, makes it a crime for any person known		
	GWW	*See Instructions on Reverse Side	/
5	51111		V
CG			