

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

N.M. 3 CONS. COMMISSION
P.O. BOX 1980
HOBBS, NEW MEXICO 88240

PROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well
☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator
HUNT OIL COMPANY

3. Address and Telephone No.
P. O. BOX 1350, MIDLAND, TX. 79702

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
Unit B, 990' FNL & 2310' FEL, Sec. 13, T25S, R37E

5. Lease Designation and Serial No.
NM-051998

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.
Carlson B-13, No. 2

9. API Well No.
30-025-11576

10. Field and Pool, or Exploratory Area
Langlie Mattix Q Gray

11. County or Parish, State
Lea Co., NM

12. **CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA**

TYPE OF SUBMISSION

- ☒ Notice of Intent
☐ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☒ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other _____

- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

SEE ATTACHED

RECEIVED
FEB 2 11 15 AM '94
CARLE AREA

14. I hereby certify that the foregoing is true and correct

Signed Don Yoder

Title Sr. Operations Engineer

Date 1/24/94

(This space for Federal or State/office use)

Approved by Shannon J. Shaw

Title PETROLEUM ENGINEER

Date 3/10/94

Conditions of approval, if any:

PROPOSED PLUGGING PROCEDURE
(Plugging Company To Be Bid)

Carlson B-13, Well No. 2
Lea County, New Mexico

1. Dump 2 sacks cement on CIBP @ 3166'.
2. Circulate hole w/ 9.5 ppg mud.
3. Set 25 sack plug @ base of salt (estimated 2300').
4. Run free point and cut-off 5-1/2" casing (estimated 1600').
5. Spot 35 sack plug across 5-1/2" casing stub.
6. Tag plug No. 3.
7. Spot 25 sack plug across 8-5/8" casing shoe @ 837'.
8. Tag plug No. 4.
9. Spot 27 sack plug from 400'-300'.
10. Spot 13 sack plug from 50'-surface.
11. Cut-off casing and weld on plate.
12. Clean-up location, bio-remediate soil if necessary.

NOTE: If casing is not pulled, will perforate squeeze hole @ 8-5/8" casing shoe and squeeze with 25 sacks cement. The cement plugs @ 400' and surface will be amended volumetrically for inside 5-1/2" casing.