Submit 3 Copies to Appropriate	State of New Mexi Ener <sub>b.</sub> , Minerals and Natural Reso	co ources Department	Form C-103 Revised 1-1-89
District Office DISTRICT I P.O. Box 1980, Hobbs, NM 88240	OIL CONSERVATION P.O. Box 2088		WELL API NO.
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	Santa Fe, New Mexico 8	7504-2088	5. Indicate Type of Lesse STATE FEE
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS ( DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		7. Lease Name or Unit Agreement Name Langlie	
1. Type of Well: OIL GAS WELL X WELL	OTHER		
2. Name of Operator Union Texas Pet			8. Well No. -B-1 9. Pool manne or Wildcat Justis (Blinebry-Tubb-Drinka
4. Well Location	Houston, TX 77252-2120 30 Feet From The East Township 255 Ram	37F	NMPM County
	10. Elevation (Show whether 1 3091 GR		
11. Check Appropriate Box to Indicate Nature of Notice, I NOTICE OF INTENTION TO: SUI			BSEQUENT REPORT OF:
		REMEDIAL WORK	
	CHANGE PLANS	COMMENCE DRILLIN	
PULL OR ALTER CASING     OTHER:	inebry-Tubb-Drinkard)XX	OTHER:	L
12. Describe Proposed or Completed Op work) SEE RULE 1103.	eraticas (Clearly state all pertinent details, a	nd give pertinent dates, inc	cluding estimated date of starting any proposed
	cative order DHC-746, we	propose to com	mingle the Blinebry-Tubb-Drinkar

The well was completed in 1959 tubb-Drinkard.. In 1970, the Tubb-Drinkard ceased to flow and the Blinebry was producing top allowable on rod pump. In 1973, difficulties in pumping the Blinebry below a packer prompted Union Texas to temporarily abandon the already shut-in tubb-Drinkard, and complete the well as a single Blinebry producer. Since 1973, the Tubb-Drinkard has never been re-entered or rod-pumped. Last production test, performed in March 1970, indicated the Tubb-Drinkard was capable of producing 108 BOPD, 886 MCFD, and 20 BWPD on an intermitter flowing 10 days a month. Commingling the Blinebry with the Tubb-Drinkard would require pulling the DR plug set in the Baker Model "N" at 5646', and milling out the Model "N" packer. Commingling and acidizing these two zones is anticipated to increase the well's productivity to its top commingled allowab s to the best of my knowledge and belief. ma Regulatory Permit Coordinators 2/20/98 30 BOPI I hereby certify that the SIGNATURE TELEPHONE NO. 713/968-36 Ken E. White TYPE OR FRINT NAME FEB 2 6 1990 --- for Conta Line)

ORIGINAL SIGNED BY JERRY SEXT	ON
APPROVED BY DISTRICT I SUPER VISOR	
CONDITIONS OF AFTROVAL, IF ANY:	

.

DATE

