Form 3160-5 UNITED STATES (June (990) DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT	FORM APPROVED
DEPARTMENT OF THE INTERIOR	FORM APPROVED
BUREAU OF LAND MANAGEMENT	
BUREAU OF LAND MANAGEMENT	Budget Bureau No. 1004-0135 Expires: March 31, 1993
	5. Lease Designation and Serial No.
	LC-060944
SUNDRY NOTICES AND REPORTS ON WELLS	
Do not use this form for proposals to drill or to deepen or reentry to a different res	ervoir.
Use "APPLICATION FOR PERMIT—" for such proposals	
SUBMIT IN TRIPLICATE	7. If Unit or CA, Agreement Designation
I. Type of Well	
Soli Gas Well Other	
2. Name of Operator	8. Well Name and No.
ARCO Oil & Gas Company	South Justis Unit "D""16
3. Address and Telephone No.	9. API Well No.
P O Box 1610, Midland, TX 79702 915 688-5674	30-025-11585
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)	10. Field and Pool. or Exploratory Area
	Justis Blbry-Tubb-Dkrd
2310 FNL & 330 FEL (Unit Letter H)	11. County or Parish, State
Sec 14-25S-37E	
	Lea County, NM
12 CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, I	REPORT. OR OTHER DATA
TYPE OF SUBMISSION TYPE OF A	
Abandonment	Change of Plans
Recompletion	New Construction
Y Subsequent Report	Non-Routine Fracturing
Final Abandonment Notice	Water Shut-Off
I other work over wellbor	Conversion to Injection
South Justis Unit	Chispose water
 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* 	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Los form)

· •

11. N 85 1

10-09-93. RUPU. POH w/CA. Mill over Mod "D" pkr @ 5763 & fish w/full recovery. CO fill to 6023 PBD. Press test csg f/4990-surf to 500# for 30 min. Add perforations f/5606-5770 (16 holes). Acidize Blinebry-Tubb-Drinkard perfs 5098-5957 in three stages w/9200 gals. RIH w/CA: 2-3/8 tbg, rods & pump to 5900. RDPU 10-19-93.

	ACCEPTINA TAN - 4 1991	Nov 4 11 27 AM
14. I hereby confify that the foregoing is true and porrect 4 1		193
signed Jahany Shields	Tide Drilling Team Leader	Date <u>11-02-93</u>
(This proce for Federal or Spite office use) Approved by Conditions of approval, if any:	_ Tide	Date

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

- Forn [®] 3160-5 (December 1989) DEPARTME ^{*-} OF BUREAU OF _AND		THE INTERIOR		FORM APPROVED MISSION Budget Bureau No. 1004-0135 Expires September 10, 1990	
		HOBBS. NEW MEXIC		LC-060944	
Do not use this for	SUNDRY NOTICES AND I m for proposals to drill or to se "APPLICATION FOR PER	C. IF INDIAN, ALLOTTEE OR TRIBE NAME			
SUBMIT IN TRIPLICATE				7. IF UNIT OR CA, AGREEMENT DESIGNATION	
				8. WELL NAME AND NO.	
2. NAME OF OPERATO	PR	South Justis Unit "D" #16			
ARCO Oil & Gas Company				9. API WELL NO. 30-025-11585	
3. ADDRESS AND TELE				10. FIELD AND POOL, OR EXPLORATORY AREA	
), Midland, TX 79702	•	5) 688-5672		
4. LOCATION OF WEL	L (Footage, Sec., T., R., M., or Survey [escription)		Justis Blbry-Tubb-Dkrd	
2310 FNL & 330 FEL (Unit Letter H)				11. COUNTY OR PARISH, STATE	
14-25S-37E				Lea	
	CK APPROPRIATE BOX(S)	TO INDICATE NATU	IRE OF NOTICE, REI	PORT, OR OTHER DATA	
TYPE O	FSUBMISSION		TYPE OF	ACTION	
XNO	TICE OF INTENT	ABANDO	NMENT	CHANGE OF PLANS	
			LETION		
su	BSEQUENT REPORT				
} FIN	AL ABANDONMENT NOTICE	L ALTERIN X Other			
		r wellbore for South Justis Unit			
Propose to we 1. 2. 3. 4.	I is directionally drilled, give subsurf orkover well bore for South Justi POH w/CA. CO fill & cmt f/5577-5763. Cut over & fish Model "D" pkr CO to 6023 PBD. Run csg integrity test. Add perforations and stimulate. RIH w/CA.	s Unit as follows: • @ 5763.	ed and true vertical depth	a for all markers and zones pertinent to this work.)*	
SIGNED (This space for Fe	hat the foregoing is true and correct en QU Lognell ideral or State office use) (OPIC SCD) 105 Č. APPROVAL, IF ANY:	TITLE _	AGENT	DATE <u>9-2-93</u> ENGINEER DATE <u>9/23/93</u>	
Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. * See Instructions on Reverse Side 1-1					
		1-1			

JULI NUBBS OFFICE

SEP 2.7 1993

PECENED

- -

WORKOVER PROCEDURE

DATE:6/18/93

WELL & JOB: SJU "D" #16 - Clean out to 6023' and bring into unit DRILLED: 10/59 LAST WORKOVER: 8/21/87 - Replace pump FIELD: South Justis Unit COUNTY: Lea. NM BY: B. G. Voigt **TD:** 6040' **PBD:** 5577' **DATUM:** 14' KB TUBINGHEAD: ? SIZE: PRESS RATING: CASING: SET @ SIZE GRADE SX CMT WEIGHT TOC SURFACE: 32.0 lb H-40 895' 390 sx 9-5/8" circ **INTER:** 7" PROD: 20-23 lb J-55 6038' 577 sx 1525' (TS) LINER: SIZE GRADE TOP BTM WEIGHT то **PERFORATIONS:** Blinebry: 5098-5223' (16 holes), 5259-5326' (7 holes), 5339-5345' (4 JSPF), 5420-32 (4 JSPF), 5476-98' (4 JSPF), 5537-66' (6 holes) 5796-5848' (4 JSPF), 5868-77' (4 JSPF), 5895-5957 (4 JSPF) Tubb/Drinkard: (Abandoned 9-22-68 by setting DR plug in Model "D" pkr at 5763' and dumping cmt on top) GRADE: J-55 **TUBING:** SIZE: 2-3/8" WEIGHT: 4.7 lb THREAD: EUE 8rd BTM'D@ 5531 MISC: MA, perf sub, SN. SN at 5498' **JOINTS:** 176

PACKER AND MISC:

HISTORY AND BACKGROUND: This well was originally drilled as a Blinebry & Tubb/Drinkard producer in October of 1959. All perforated intervals have been acidized and fraced. In September of 1968, the Tubb/Drikard perforations were abandoned by setting a "DR" plug in the Baker Model "D" packer at 5763' and dumping 17 sx of cement on top of the packer. Currently the well is a producer in the Blinebry.

SCOPE OF WORK: Clean well out to fish, cut over and retrieve fish, & clean out to original PBD or 6023'

PROCEDURE

- 1. MIRU PU. POOH w/ rods and pump. ND WLHD. NU BOP. POOH with completion assembly.
- 2. RIH with 6-1/4" MT bit, DC's, and 2-7/8" WS to top of Blinebry perforations at 5098'. Break circulation using bridging material. Continue in hole and tag fill at 5577'. Clean out fill to top of fish at 5763'. Circulate hole clean and POOH.
- 3. RIH with 6-1/4" x 4-7/8" KR shoe and washover assembly on 2-7/8" WS. Cut over Baker Model "D" packer and clean well out to original PBD of 6023'. Attempt to jam fish in washpipe. POOH with fish.
- 4. RIH with Baker Model "G" RBP and set at 5000'. Conduct casing integrity test to 500 psi. Relatch RBP, release, and POOH.
- Add perforations and stimulate. RIH with completion assembly (MA, perf sub, SN, TAC, and tubing) per F/P Engineering design. ND ₹ 5. BOP. NUWLHD. RIH with pump and rods per F/P Engineering design.
- 6. RD PU. TOTPS.

Permian Team Drilling Engineer

OFFICE

SEP 27 1993

RECEIVED



OFFICE

SEP 2.7 1913

RECEIVED