

ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISIC  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT - 1" (FORM C-101) FOR SUCH PROPOSALS.

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	5. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
2. Name of Operator ARCO Oil and Gas Company	6. State Oil & Gas Lease No.
3. Address of Operator P.O. Box 1610, Midland, Texas 79702	7. Unit Agreement Name
4. Location of Well UNIT LETTER C 330 FEET FROM THE North LINE AND 1650 FEET FROM THE West LINE. SECTION 14 TOWNSHIP 25S RANGE 37E NMPM.	8. Farm or Lease Name Stuart "A" WN
15. Elevation (Show whether DF, RT, GR, etc.) 3129 GR	9. Well No. 1
	10. Field and Pool, or Wildcat Langlie Mattix SP. Qn
	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2-14-87. RU PU. Unable to pull tbg. Clean out @ 2360'. POH w/77 jts 2-3/8" tbg. RIH w/OS. Rec 960' 2-3/8" tbg. Full Rec. P&A as follows:

Plug	Interval	Cmt	Remarks
1	2300-3395'	300 sx	Set pkr @ 2800'. Sqz w/300 sx. POH to 2300 & rev out 15 sx. POH w/pkr.
2	1929-2100	100 sx	Tag TOC @ 2306'. Perf @ 2300. Unable to pump in. Perf @ 2100. Est PIR. CR @ 1989 w/60' cmt on top.
3	0-900	185 sx	Perf @ 993. Would not circ out ann. perf @ 900. Circ cmt to surf out 5-1/2" x 7-5/8". Closed 7-5/8" csg & pump 15 sx into perf @ 993'.

RD PU. Install dry hole marker. Well P&A'd 2-21-87.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Ken W. Gosnell TITLE Engr. Tech. 915-688-5672 DATE 3-31-87

APPROVED BY [Signature] TITLE OIL & GAS INSPECTOR DATE MAY 13 1987

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED  
APR 2 1987  
HOBBS OFF