

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT-" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER		7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR Meridian Oil Inc		8. FARM OR LEASE NAME Prichard
3. ADDRESS OF OPERATOR P.O. Box 51810, Midland, TX 79710-1810	3a. AREA CODE & PHONE NO. (915)688-6943	9. WELL NO. 1
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface N, 660' FSL & 1980' FWL		10. FIELD AND POOL, OR WILDCAT Jalmat (Tansill-Yates-7Rvr)
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec 15, T25S, R37E
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3085 GR	12. COUNTY OR PARISH Lea
		13. STATE NM

### 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

#### NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

#### SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Refrac Yates & Install Pump.

6/4/91 Tbg stuck in hole. Fish tbg.

6/5/91 Pulled part of fish.

6/6/91 Wash over fish. Wash out to 2940'. Circ hole clean. Recovered all of fish.

6/7/91 Press annulus to 1000#.

6/9/91 Frac w/ 18,900 gals of 50-Quality CO2 foam, 72,600# 1/20 brady.

6/11/91 Good returns thru out until pipe stuck. TOH. TIH & screw into fish.

6/12/91 Circ w/ foam to 2940', btm of fish. Could not get shoe to drill past this point. recover fish.

6/13/91 RIH w/ 2 3/8" tbg hung @ 2772'. RIH w/ 2" x 1 1/2" x 12' RWBC. Turn to production.

6/29/91 PU to 2895'. Hung off tbg. Re-ran pump & rods. No pump action. Replace pump & filter.

6/30/91 Release to production.

18. I hereby certify that the foregoing is true and correct

SIGNED

*Kelvin R. Scholz*

TITLE

Production Asst

DATE

04/01/92

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side