

MIDLAND E & P DIVISION

WELL WORK RECOMMENDATIONS

Proposals for Well Reconditioning and Subsurface Maintenance
Workovers, Expense DD's, PB's, and Conversions

Lease: 4113 W. Stuart-Turner 9 Well No. 147
Field: Longhorn-Martin
County: Lea State: New Mexico

RECOMMENDED PROCEDURE:

6- Shut the well in for 2 hrs.

7- Swab clean up and test the well as required.

8- Put the well on production.

JES/HHH/WH
8-1-67