

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30 025 11639
5. Indicate Type of Lease STATE ☐ FEE ☒
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name WOOLWORTH B
8. Well No. 1
9. Pool name or Wildcat JALMAT YATES 7R (GAS)
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3114'

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☐ GAS WELL ☒ OTHER
2. Name of Operator Texaco Exploration and Production Inc.
3. Address of Operator P. O. Box 730 Hobbs, NM 88240
4. Well Location Unit Letter <u>D</u> : <u>330</u> Feet From The <u>N</u> Line and <u>990</u> Feet From The <u>W</u> Line Section <u>17</u> Township <u>25S</u> Range <u>37E</u> NMPM LEA

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: ☐	PLUG AND ABANDONMENT ☒
	CASING TEST AND CEMENT JOB ☐
	OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well abandon 05-18-93. Abandonment report on reverse side.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE Engr Asst DATE 06-29-93
TYPE OR PRINT NAME L.W. Johnson TELEPHONE NO.

(This space for State Use)

APPROVED BY [Signature] TITLE OIL & GAS INSPECTOR DATE [Signature]
CONDITIONS OF APPROVAL, IF ANY:

DASSIOL WELL SERVICING

INCORPORATED

Texaco, Inc.
Woolworth "B" #1

5/12/93 Move in, rig up, work on wellhead, shut down.
5/13/93 Put on BOP, pull and lay down 97 joints
2 7/8 tubing, run bit and scraper to 2750',
set, circulate mud, spot 30 sacks cement
2750' - 2570', pull tubing out, shut down.
5/14/93 Run cement bond log, good cement from t.d.
to 700', test casing with packer, leak at
700' also 400, run tubing in hole to 1250',
spot 25 sacks, pull tubing.
5/17/93 Run tubing, tag cement at 1067', cement plug
from 1250' - 1067', pull tubing 725, circulate
255 sacks, inside and outside to surface,
squeeze 25 sacks down 7", shut in, shut down.
5/18/93 Cut off wellhead, put in marker, fill
cellar, move off.

505-392-6591 • P.O. BOX 2545 • HOBBBS, NEW MEXICO 88241

HOBBBS, NEW MEXICO (505) 392-6591 (915) 523-4420
ANDREWS, TEXAS

LOCATIONS

EUNICE, N. MEXICO (505) 394-2557 (915) 685-8555
MIDLAND, TEXAS