

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-101
Revised 10-1-73

CS		
CST		
ANTENNA		
TLC		
JG.S.		
AND OFFICE		
PERATOR		

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO REELECT OR PLUG SALS TO A DIFFERENT DEPTH/SECTION.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.

☒ YES ☐ NO OTHER _____

Texaco Producing Inc.

P.O. Box 728, Hobbs, NM 88240

IT LETTER J 1980 FEET FROM THE South LINE AND 1980 FEET FROM

East LINE, SECTION 18 TOWNSHIP 25 RANGE 37E MPM.

15. Elevation (Show whether DF, RT, CR, etc.)

3108 K.B.

5a. Indicate Type of Lease

State

Fee ☒

3. State Oil & Gas Lease No.

1. Unit Agreement Name

South Langlie Jal Unit

1. Form of Lease Name

9. Well No.

20

10. Field and Foot, or Wildcat

Jalmat (Oil)

12. County

Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: | SUBSEQUENT REPORT

ON REMEDIAL WORK ☐
 RAPIDLY ABANDON ☐
 OR ALTER CASING ☐

PLUS AND ABANDON

REMEDIAL WORK

COMMENCE SAILING 8PM.

CASING TEST AND CEMENT JOBS

OTHER

ALTERING CASING

PLUS AND ASSIGNMENT

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1/03/85 - Rig up. Pull rods and tubing.
- 1/04/85 - Clean out 5½" casing to 2853'. Ream out 4½" slotted liner from 2853' to 3356'. Fill 3346' to 3356'.
- 1/05/85 - Frac 4½" liner slots 2885' to 3356' w/2000 gal. 15% NEFE acid 25,000 gal. 30# x-linked 2% gelled KCL water w/55,000# 12/20 sand in 2 equal stages w/750# rock salt block down 2 7/8" tubing. Max. press. - 4100 psi, min. press. - 1970 psi, ISIP - 600 psi.
- 1/6&7/85 - Wash & drill sand from 2847' to 3356'.
- 1/10/85 - POH. Rerun tubing & rods. Rig down. Put on pump.
- 12/15/85 - Well tested 7 BOPD, 75 BFWPD, 257 GOR.

W.B. Ch

District Oper. Mgr.

DATE 01-07-86

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT 1 SUPERVISOR

JAN 16 1986

RECEIVED
JAN 15 1986
O.C.D.
HOBBS OFFICE