	• 📬 👌 🖓 🖕	tage the second s	$\sim$
NO. OF COPIES RECEIVED	]	1	. C, Born C-103
DISTRIBUTION			C-102 and C-103
SANTA FE	NEW MEXICO OIL CONSE	JUN 11 51	All 'Effective 1-1-65
FILE			
U.S.G.S.			5a. Indicate Type of Lease
	-		
OPERATOR			5. State Oil & Gas Lease No.
SUNDE	RY NOTICES AND REPORTS ON DEPENDENT OF PLUG BA	WELLS	
(DO NOT USE THIS FORM FOR PR USE "APPLICA"	OPOSALS TO DRILL OR TO DEEPEN OR PLUG BA TION FOR PERMIT -** (FORM C-101) FOR SUCH	PROPOSALS.	7. Unit Agreement Name
1.			7. Unit Agreement Ivanie
OIL GAS WELL	OTHER-		8. Farm or Lease Name
2. Name of Operator			0.1 4
Sun Oil	l Company		9. Well No.
3. Address of Operator	-		
P. O. H	Box 2792, Odessa, Texas 70	9760	2 10. Field and Pool, or Wildcat
4. Location of Well			
UNIT LETTER	660 FEET FROM THE Bast	LINE AND 1980 FEET FROM	11111111111111111111111111111111111111
THE South LINE, SECT	TION TOWNSHIP 25 ;	<u>а Range 37 на пмрм.</u>	<i>\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\</i>
	15. Elevation (Show whether	DE RT CR etc.)	12. County
	3050 Cr.		
<sup>16.</sup> Check	Appropriate Box To Indicate N	ature of Notice, Report or Ut	ner Data
NOTICE OF	INTENTION TO:	SUBSEQUEN	T REPORT OF:
			ALTERING CASING
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	PLUG AND ABANDONMENT
TEMPORARILY ABANDON	<b>L</b> J	COMMENCE DRILLING OPNS.	
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB	
	۲-٦	OTHER	
OTHER			

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1903.

5-11-66 pulled 22" tubing, wkg. bbl., and mud anchor. Removed well head - installed BOP. Western ron Gamma Ray - Neutron log 2300 to 2965'. Set Baker Hodel NolBP at 2812 with 1 sack cement on top. Loaded 7" casing w/brine and tested 7" cusing and 2 3 12004, 30 minutes, 5-13-66 western perforated 7" casing w/5" cased gun, 20.6 grm J-2 charge .50" hole, from 0...... 2704-2707, 2714-2716, 2720-30, 2752-75, 2778-85 and 2798-2808 w/2 JSFF by Garma Ray-Neutron log. Log indicated shots in proper interval. Han 2" tubing, packer, holddown and anchor. 5-14-55 Howco treated perfs. ( intervals from 2704 to 2808 w/500 gul. 15% NE acid down 2" tubingw/ seat C 2808. Spotted acid across peris. and formation started taking fluid. Flushed w/10.8 bbl. brine. Pulled tubing, packer and holddown. Howco treated perfs. at intervals from 2704 to 2808 down 7" casing w/10,000 gal. gelled brine,  $1\frac{1}{20}$  sd/gal. 1st stage 5000 gal., formation taking fluid. Added 300# salt for block between stages. Formation would not take fluid. Lan tubing found bridge. Fulled tubing, - 2nd stage - frac. 5000 gal. brine 12#sd/gal. Flushed w/100 bbl. brine. 5-15-66 ran tubing, packer. Swabbing. 5-17-66 Chemical Engineers pumped 120 bbls. fresh water w/10 gal. (B-1) NM chemical w/non-swelling additive. Swabbing. THE COMMISSION MUST BE NOTIFIED Workover unsuccessful. Well shut in for further evaluation. TO THE WELL STATUS AND YOUR PLANS FOR THIS WELL.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED YELdim	TITLE Area Superintenaent	DATE
	E CARLES E C	JUN 1 5 1966