

NEW MEXICO OIL CONSERVATION COMMISSION
Santa Fe, New Mexico

MISCELLANEOUS NOTICES

Submit this notice in TRIPLICATE to the District Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

Indicate Nature of Notice by Checking Below

NOTICE OF INTENTION TO CHANGE PLANS		NOTICE OF INTENTION TO TEMPORARILY ABANDON WELL		NOTICE OF INTENTION TO DRILL DEEPER	
NOTICE OF INTENTION TO PLUG WELL		NOTICE OF INTENTION TO PLUG BACK		NOTICE OF INTENTION TO SET LINER	
NOTICE OF INTENTION TO SQUEEZE		NOTICE OF INTENTION TO ACIDIZE		NOTICE OF INTENTION TO SHOOT (Nitro)	
NOTICE OF INTENTION TO GUN PERFORATE		NOTICE OF INTENTION (OTHER)		NOTICE OF INTENTION (OTHER) Workover	X

OIL CONSERVATION COMMISSION
SANTA FE, NEW MEXICO

Odessa, Texas
(Place)

12-20-61
(Date)

Gentlemen:

Following is a Notice of Intention to do certain work as described below at the B. T. Lashart

Sun Oil Company Well No. 3 in P
(Company or Operator) (Unit)
SE $\frac{1}{4}$ SE $\frac{1}{4}$ of Sec. 20, T. 25-S, R. 37-E, NMPM., Crosby Devonian Pool
(40-acre Subdivision)
Lea County.

FULL DETAILS OF PROPOSED PLAN OF WORK
(FOLLOW INSTRUCTIONS IN THE RULES AND REGULATIONS)

Move in, rig up load hole w/brine water. Dismantle head, install BOP & pull 2" tubing. Run 2" tubing w/Baker milling tool & drill out Model "D" packer. Pull tubing. Run 2" tubing w/4 5/8" bit and casing scraper and clean out to TD of 8938 and pull tubing. Run tubing w/Lynes straddle packers. Space packers to set elements at 8806' and at 8868'. Swab each set of perfs. to determine zone or zones of water entry. Pull pkrs and tbg. Squeeze off zone of wtr entry as indicated on swabbing tests w/slo set cement w/the volume depending on length of zone to be squeezed. Re-squeeze if necessary and WOC 12 hours. Drill out cement and retainers. Set Baker Model "D" pkr. at 8700'. Run 2" tubing. Swab in and test. Plan to start this work 12-26-61.

Approved _____, 19____
Except as follows:

Approved
OIL CONSERVATION COMMISSION

By _____
Title _____

Sun Oil Company
Company or Operator

By O. N. Williams

Position Area Superintendent
Send Communications regarding well to:

Name Sun Oil Company

Address Box 2792, Odessa, Texas