

NEW MEXICO OIL CONSERVATION COMMISSION
Santa Fe, New Mexico

MISCELLANEOUS REPORTS ON WELLS

Submit this report in triplicate to the Oil Conservation Commission or its proper agent within ten days after the work specified is completed. It should be signed and sworn to before a notary public for reports on beginning drilling operations, results of shooting well, results of test of casing shut-off, result of plugging of well, and other important operations, even though the work was witnessed by an agent of the Commission. Reports on minor operations need not be signed and sworn to before a notary public. See additional instructions in the Rules and Regulations of the Commission.

Indicate nature of report by checking below:

REPORT ON BEGINNING DRILLING OPERATIONS		REPORT ON REPAIRING WELL	
REPORT ON RESULT OF SHOOTING OR CHEMICAL TREATMENT OF WELL		REPORT ON PULLING OR OTHERWISE ALTERING CASING	
REPORT ON RESULT OF TEST OF CASING SHUT-OFF	X	REPORT ON DEEPENING WELL	
REPORT ON RESULT OF PLUGGING OF WELL			

Roswell, New Mexico

November 29, 1937

Place

Date

OIL CONSERVATION COMMISSION,
Santa Fe, New Mexico.

Gentlemen:

Following is a report on the work done and the results obtained under the heading noted above at the _____


HARRY LEONARD Lanehart Well No. 4 in the
Company or Operator Lease
NW 1/4 of Sec. 21, T. 25S, R. 37E, N. M. P. M.,
Jal Field, Las County.

The dates of this work were as follows: November 25, 1937

Notice of intention to do the work ~~was~~ [was not] submitted on Form C-102 on _____ 19____
and approval of the proposed plan was [was not] obtained. (Cross out incorrect words.)

DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED

Ran 1226' of 8-1/4" 32# Casing and cemented with 308 sacks;
stood cemented for 72 hours; drilled plug November 28;
Result - complete shut off.



DUPLICATE

Witnessed by _____ Name _____ Company _____ Title _____

Subscribed and sworn to before e this 29

day of November, 19 37

Edna Mae Bear

Notary Public

My Commission expires May 7, 1941

I hereby swear or affirm that the information given above is true and correct.

Name HARRY LEONARD

Position Secretary

Representing HARRY LEONARD

Address Roswell, N. M.

Remarks:

Guy Shepard Name
Oil & Gas Inspector Title

DEC 1 - 1937

