

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

MAY 5 8 52 AM '69

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State ☐ Fee ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Union Texas Petroleum Corporation	8. Farm or Lease Name Lanehart
3. Address of Operator 1300 Wilco Building, Midland, Texas 79701	9. Well No. 1
4. Location of Well UNIT LETTER L 2310 FEET FROM THE South LINE AND 990 FEET FROM THE West LINE, SECTION 21 TOWNSHIP 25-S RANGE 37-E N.M.P.M.	10. Field and Pool, or Wildcat Jalmat
11. Elevation (Show whether DF, RT, GR, etc.) 3054 GL	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Run open end tubing to 2928' - TD. Spot 100' cement plug from 2928' to 2828' - (Fill 27' of open hole and 73' of 5 1/2" casing).
- Fill hole with mud laden fluid. Pull tubing then fill hole to within 20' of surface with mud laden fluid.
- Fill top 20' of 5 1/2" casing with cement.
- Weld steel plate across top of all casing strings, (16", 8 5/8", 7" & 5 1/2"). Install 4" O. D. well marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED R. W. Manry TITLE District Drilling Supt. DATE May 2, 1969

APPROVED BY [Signature] TITLE SUPERVISOR DATE 1969

CONDITIONS OF APPROVAL, IF ANY: