

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TR
(Other instructi
verse side)

CATE
on re

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

RECEIVED

JUN 25 10 36 AM '91

CARLSON
AREA

5. LEASE DESIGNATION AND SERIAL NO.

LC-032579-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

HARRISON

9. WELL NO.

3

10. FIELD AND POOL, OR WILDCAT

LANGLIE MATTIX SR-QU-GH

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

SEC. 22, T25S, R37E

12. COUNTY OR PARISH

LEA

13. STATE

NEW MEXICO

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

PENROC OIL CORPORATION

3. ADDRESS OF OPERATOR

P.O. BOX 5970, HOBBS, NEW MEXICO 88241

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)

At surface

1650' FSL & 1650' FEL of SECTION 22, T25S, R37E
LEA COUNTY, NEW MEXICO

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, OR, etc.)

3061 DF

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐
☐
☐
☐

PULL OR ALTER CASING

☐
☐
☒
☐

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐
☐
☐

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

7" @ 3226'

Proposed: Set CIBP @ 3150'. Spot 25x8.

on cement on top. Cut & pull

2100' of 7" CSG. Spot cement

plug 2050'-2150'. Spot 508x4.

plug @ the base of 9 5/8" (1000'-1100'), TAG PLUG

50' SURFACE
Spot 1108x. Plug @ surface, ERECT DRY HOLE MARKER

Clean up location and seed.

* USE 14.8 PP9 CLASS "C" CEMENT SLURRY FOR CEMENT PLUGS.

* Fill WELLBORE BETWEEN PLUGS WITH 4 PP9 LADEN MOD.

18. I hereby certify that the foregoing is true and correct

SIGNED

John A. McArthur

TITLE

President

DATE

6/21/81

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

7-1-91

CONDITIONS OF APPROVAL, IF ANY:

* NOTIFY BLM AT 393-3612 PRIOR TO COMMENCING PLUGGING OPERATIONS.

*See Instructions on Reverse Side

RECEIVED

JUL 09 1991

800
H0808 11/1/91