| Form 9-231 (May 1963) | UNITED STATES RTMF OF THE INTERI | SUBMIT IN TRIPLICATE* (Other instruction of re- | Dauger Daiska | No. 42-R142- |
|---|--|--|--|--------------------------------|
| GECLOGICAL SURVEY | | | 5. LEASE DESIGNATION AND SERIA! NO. | |
| HURRY OFFICE O. C. C. | | | NM 0766 6. IF INDIAN, ALLOTTEE OR THIBE NAME | |
| SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PHIMAL" IN PROPOSOBLE.) | | | | |
| OIL FE GAS | | | 7. UNIT AGREEMENT NAME | |
| WELL X WELL OTHER 2. NAME OF OPERATOR | | | | |
| UNION TEXAS PETROLEUM CORPORATION | | | 8. FARM OR LEASE NAME | |
| 3. ADDRESS OF OPERATOR | | | Carlson "B" | |
| 1300 Wilco Bldg., Midland, Texas 4. Location of Well (Report location clearly and in accordance with any State requirements.* See also space 17 below.) | | | 10. FIELD AND POOL, OR W | ILDCAT |
| At surface | | | Justis (Bl | |
| 660* | FSL & 330' FEL | | 11. SEC., T., R., M., OR BLK. SURVEY OR AREA | |
| 14. PERMIT NO. | 15. ELEVATIONS (Show whether DF, | THE CO. L. L. | Sec. 23, T-25-9 | s, R-37- |
| | 3086 DF | RT, GR, etc.) | 12. COUNTY OR PARISH 13 | |
| 16. Charle | | | | N. Mex. |
| | Appropriate Box To Indicate N | ature of Notice, Report, or C | Other Data | |
| | VIENTION TO: | SUBSEQU | JENT REPORT OF: | |
| FRACTURE TREAT | PULL OR ALTER CASING MULTIPLE COMPLETE | WATER SHUT-OFF | REPAIRING WELI | |
| SHOOT OR ACIDIZE X | ABANDON* | FRACTURE TREATMENT SHOOTING OR ACIDIZING | ALTERING CASIN | G |
| REPAIR WELL X | CHANGE PLANS | (Other) | ABANDONMENT* | |
| (Other) | | | of multiple completion on vetton Report and Log form.) | |
| Perf Blinebry (Upp | operations (Clearly state all pertinent ectionally drilled, give subsurface locations) W/one ½" hole per f | oot @ following dent | hs 5042=50821 | starting and d zones perti- |
| 2171-2128. 21/0.~ | 5230'. Run RBP and set | : @ 5250'. Acidize n | ew perfs W/1000 | |
| gal 15% HCl NE. F | rac W/30,000 gal 9# syn | thetic gelled brine | W/sand concentrat | ion |
| each. Run dual tu | /gal to $2\#/$ gal in three bing strings and conduc | staged treatments o | f 10,000 gallons | |
| production. | orng strings and conduct | t packer teakage tes | c. Place on | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | 9 | | |
| | | | | |
| | | | | |
| | | <u>.</u> | | |
| | | | | |
| | • | 4. 4. 2. 2. | | |
| | | | | |
| 2 | | ساه ۱ و ۱ م ۱ م | | • |
| 8. I hereby certify that the foregoing | g is true and correct | | | |
| | anry TITLE Dis | t. Drilg Supt. | DATE June 17 | <u>, 1968</u> |
| (This space for Federal or State of | office use) | . 12 | :01 | |
| APPROVED BY | TITLE | PROVE | DATE | |
| CONDITIONS OF APPROVAL, IF | ANY: | 1 9 1968 | | |

*See Instructions on Reverse Side A. F. Brigines DISTRICT ENGINEER