

(SUBMIT IN TRIPLICATE)

U. S. Land Office... Lm. Griggs

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Lease or permit No. 032579-A

C. M. Carlson
"Harrison #5"

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT..... <input checked="" type="checkbox"/>
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

September 7, 1943.

Well No. 5 is located 1230 ft. from S line and ft. from W line of sec. 23

5-1/4 of 5-1/4 sec. 23 250 37 N.M.P.M.
(H Sec. and Sec. No.) (Twp.) (Range) (Meridian)

Langlois Wildcat Loc New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3674 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

T.D. 5026'. Hole was filled with 10.5% mud and a cement plug was spotted from 4846' to 4750'.

5 1/2" 15# H-40 Smls casing was shot off at 4400', 4136' were recovered.

Cement plugs were then placed from 4325' to 4200' w/40 sacks cement

4000' to 3750' w/80 sacks cement

3290' to 3050' w/80 sacks cement

2350 to 2275' w/30 sacks cement

8-5/8 of salt plug was allowed to set 72 hours at which time steel line measurement showed top of plug to be 2250'.

8-5/8" 28# H-40 Smls casing was shot off at 1700' and 1011' were recovered.

A cement plug was then placed from 1200' to 1000'.

All 13" casing was left in hole.

A regulation marker was cemented in top of hole and ground surface restored to its original level.

(Indicate that plan of work must receive approval in writing by the Geological Survey before operations may be commenced.)

Company Anderson-Prichard Oil Corporation

Address Box 1697, Hobbs, New Mexico

By Frank Gray

Title District Supt.