

of the Carlson Federal "A" No. 2. A copy of Administrative Order DHC-658 dated July 29, 1987, is attached. No fluid compatibility problems have been experienced with any of these operations over the years.

Additionally, the Blinebry and the Tubb/Drinkard in Hendrix's Wimberly #3, which is one location northeast of the Carlson Federal "A" #2, are downhole commingled. The well does not appear to have any fluid compatibility problems.

h. Commingling Computations - Attached

i. Allocation of Production - based on latest production tests

	<u>Oil</u>	<u>Gas</u>	<u>Water</u>
Blinebry	77%	40%	40%
Tubb	23%	60%	60%
Total	100%	100%	100%

j. Notification of Offset Operators

A copy of the notice sent to offset operators and the Bureau of Land Management, the return receipts, and the BLM's approval are attached.