

Well Name & Number: Carlson Federal "A" 2

Treatments and Workovers (continued)

Date:

4-70	Set plug in 415-D PKR at 5773. Pumped 2 SA SN + 2 SK cmt. T/BK P+H'd.
6-80	Acidized Bly 5203-5376 w/ 3000 gals 15% NEA. Perf'd Bly at 5105, 11, 19, 33, 36, 44, 52, 57, 63 Sg'd parts 4968-5020' w/ 50 SA Bly parts new 5203-5386, P 580 40merf, 21BW
9-80	Acidized Bly 5105-5163 w/ 1000 gals Frac'd " " w/ 15,000 gals gel acid, 14,000 gals gel 9 # BW, 12,000 # 40/60 salt. Tested 16BW, 42BW, 47merf
2-86	Holes in tbg 2 jts above SN - Replaced. Now 172 jts 2 3/8" tbg in hole. SN at 5341'
6-86	Shut-in
1-88	CO to 6018 Perf Drinkard 5967-6007' Acidize w/ 2500 gals. 1P P 7BW, 105BW, 1merf.
3-88	Set RBP at 5952. Acidize Tubh parts 5820-5926 w/ 5000 gals. POH w/ RBP. 1P P 6BW, 95BW, 6merf.
4-88	Set RBP at 5945. Pump Tubh parts 5820-5926 3BW-32BW, 25merf. (Acidized w/ 5000 gals)
5-88	Set RBP at 5509'. Acidize Blinbury 5105-5386 w/ 16,000 gals 70 quality foamed acid.

RECEIVED

AUG 25 1988

CCO
HOBBS OFFICE