Form \$160-6 (July 1989) (Formerly 9-331)

CONDITIONS OF APP

CONTACT RECEIVI

BLM Roswell District Modified Form No.

5-692

OFFICE FOR NUMBER UN! D STATES NM060-3160-4 OF COPIES REQUIRED DEPARTMENT OF THE INTERIOR (Other instructions on reverse LEASE DESIGNATION AND SERIAL NO. BUREAU OF LAND MANAGEMENT NM-0766 IF INDIAN, ALLOTTEE OR TRIBE NAME SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT-" for such proposals.) UNIT AGREEMENT NAME METT [GAS WELL OTHER API-NO. 30-025-14708 NAME OF OPERATOR FARM OR LEASE NAME MERIDIAN OIL INC. CARLSON FEDERAL 3a. AREA CODE & PHONE NO. ADDRESS OF OPERATOR WELL NO. P.O. Box 51810, Midland, TX 79710-1810 915-688-6898 3 LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* 10. FIELD AND POOL, OR WILDCAT See also space 17 below.) LANGLIE MATTIX 7R-QN At surface 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA -1989' FSL & 660' FEL 66015 23, T-25-S, R-37-E PERMIT NO 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 12. COUNTY OR PARISH 13. STATE 3073.6' GR LEA N.M. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF PULL OR ALTER CASING WATER SHUT-OFF REPAIRING WELL FRACTURE TREAT MULTIPLE COMPLETE FRACTURE TREATMENT ALTERING CASING Х SHOOT OR ACIDIZE ABANDON* SHOOTING OR ACIDIZING ABANDONMENT* REPAIR WELL CHANGE PLANS (Other) (NOTE: Report results of multiple completion on Well (Other) Completion or Recompletion Report and Log form.) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this NOTIFY BLM 24 HRS BEFORE COMMENCING WORK. RIH W/CASING SCRAPER TO +/- 2900'. SET CMT RETAINER ON TUBING @ +/- 2900'. SQUEEZE OPEN HOLE WITH 65 SX (22 SX EXCESS) CL. C CMT. STING OUT OF RETAINER AND SPOT 10 SX ON PLUG. PULL UP AND CIRC HOLE WITH 9 PPG GELLED BRINE. PULL UP TO 2200', SPOT PLUG ACROSS BASE OF SALT AT 2070' - 2200'. USE 25 SX CMT. PULL UP TO 1310' AND SPOT PLUG ACROSS TOP OF SALT AT 1190' - 1310'. USE 25 SX. PULL UP TO 360' AND SPOT PLUG ACROSS SURFACE CASING SHOE AT 250' - 360'. USE 25 SX. PERFORATE FOUR (4) SQUEEZE HOLES AT +/- 50'. OPEN BRAIDEN HEAD AND CIRC CMT BY PUMPING DOWN 7" CSG. USE 20 SX TO SET SURFACE PLUG. CUT CASING OFF 3' BELOW GROUND LEVEL AND INSTALL P&A MARKER. RIP AND RECLAIM LOCATION. 100 18. I hereby that foregoing CONNIE L. MALIK 4/14/92 SIGNED DATE (This space for


*See Instructions on Reverse Side

PETROLEUM ENGINEER

KLM 4/9/92

MERIDIAN OIL

CARLSON FED. NO. 3 LANGLIE MATTIX FIELD LEA COUNTY, NEW MEXICO



KLM 4/9/92

MERIDIAN OIL

CARLSON FED. NO. 3 LANGLIE MATTIX FIELD LEA COUNTY, NEW MEXICO

