

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 87240
District II
811 South First, Artesia, NM 87210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Geology, Minerals and Natural Resources

Form C-103
Revised March 25, 1999

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

WELL API NO.	30-025-11716
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>	
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name WIMBERLY WN	
8. Well No.	001
9. Pool name or Wildcat JAMAT-TAN-YATES-7 RIVER (GAS)	
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3090 GR	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH
PROPOSALS.)

1. Type of Well:
Oil Well ☐ Gas Well ☒ Other

2. Name of Operator HENRY PETROLEUM LP

3. Address of Operator 3525 ANDREWS HIGHWAY - SUITE 200
MIDLAND TX 79703-5000

4. Well Location
Unit Letter F 1980 feet from the NORTH line and 1980 feet from the WEST line
Section 23 Township 25-S Range 37-E NMPM LEA County NEW MEXICO

10. Elevation (Show whether DR, RKB, RT, GR, etc.)
3090 GR

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☒ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOBS ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and proposed work). SEE RULE 1103. For Multiple Completions: Attach diagram of proposed completion or recompletion.

01) RU ON WELL AND TIH TO PBTD 2890' - PULL UP 20' OFF BOTTOM AND SWAB WELL & REPORT RESULTS TO OFFICE.

02) IF ENCOURAGED BY GAS ANALYSIS AND BY SWABBING THEN RUN RODS AND TUBING AND INSTALL PUMPING UNIT.

03) IF BAD RESULTS THEN DRILL OUT CEMENT AND CIBP AT 2900'.

04) RUN GR-NEUTRON LOG AND VERIFY WHERE TO PERF. COMPARED TO OLD PERFS. (3044-3322').

05) RE-PERFORATE LANGLIE FROM 3044-3222 & ACIDIZE LANGLIE PERFS BELOW A PACKER WITH 5000 GALS. 15% NEFE HCL.

06) SWAB BACK SPENT ACID AND REPORT RESULTS TO OFFICE - BASED ON RESULTS IF MAKING FLUID AND GAS THEN RUN TUBING, PUMP, RODS AND PUT WELL TO PUMPING - CONNECT WELL TO TESTER.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Roy R. Johnson TITLE REGULATORY TECH. DATE 01/20/2003

Type or print name ROY R. JOHNSON Telephone No. (915)694-3000

(This space for State use)

APPROVED BY _____ TITLE _____ DATE JAN 24 2003

Conditions of approval, if any:

ORIGINAL SIGNED BY
GARY W. WINK
OC FIELD REPRESENTATIVE II/STAFF MANAGER