

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-11718
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name South Justis Unit "E"
8. Well No. 21
9. Pool name or Wildcat Justis Bly Tubb Drkd
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3085' KB

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER
2. Name of Operator ARCO Permian
3. Address of Operator P.O. Box 1710, Hobbs, New Mexico 88240
4. Well Location Unit Letter L : 1980 Feet From The S Line and 990 Feet From The W Line Section 24 Township 25S Range 37E NMPM Lea County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: Add Perfs and Acidize <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD: 7000' PBD: 6721' PERFS: 4981-5987'

12/06/96: WIH 2 1/2-7/8" workstring to 5955'. Tested tbg @ 5000# below slips. POH w/tbg. WIH w/4" guns perf 1 SPF 4981-5028, 20 holes.

12/07/96: WIH w/PPI pkr @ 5030'. Acidize new perfs from 4981-5028 w/50 gals/ft 15% NEFE HCL, total 1000 gals. Acidize existing perfs from 5047-5987 w/1000 gals 15% NEFE HCL. POH w/tbg, pkr. WIH w/2-7/8" tbg, pump, & rods. Tested and loaded tbg to 500#.

~~12/06/96: WIH 2 1/2-7/8" workstring to 5955'. Tested tbg @ 5000# below slips. POH w/tbg. WIH w/4" guns perf 1 SPF 4981-5028, 20 holes.~~

~~12/07/96: WIH w/PPI pkr @ 5030'. Acidize new perfs from 4981-5028 w/50 gals/ft 15% NEFE HCL, total 1000 gals. Acidize field~~

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kellie D. Murrish TITLE Admin. Asst. DATE 3-25-97
TYPE OR PRINT NAME KELLIE D. MURRISH TELEPHONE NO. 394-1649

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE MAR 28 1997
CONDITIONS OF APPROVAL, IF ANY: