

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☒ gas well ☐ other

2. NAME OF OPERATOR

Getty Oil Company

3. ADDRESS OF OPERATOR

P. O. Box 728, Hobbs, NM. 88240

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

990' FEL & 1980' FNL

AT SURFACE:

AT TOP PROD. INTERVAL:

AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

CHANGE ZONES ☐

ABANDON* ☐

(other)

5. LEASE

LC-032650 (b)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

A.B. Coates

9. WELL NO.

24

10. FIELD OR WILDCAT NAME

Justis Blinebry

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 24, T-25-S, R-37-E

12. COUNTY OR PARISH 13. STATE

Lea New Mexico

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)

3081' (DF)

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Rigged up. Remove Dual Well Head.
2. Set Cement retainer @ 5060'. Squeeze Blinebry perfs 5218-5476 & Comminge perfs. 5429-5439'. West csg string perfs 5160-5439', Comminge perfs 5160-5170' & East csg string perfs 5175-5060'. W/20 sx class H Cement. Left 50' Cement on top of retainer.
3. Cut 2 7/8" Csg String @ 1685' & Pull.
4. Spot 40 sx class H Cement plug from 1774'-1714'.
5. Spot 180 sx Class H Cement plug from 1747-1497'.
6. Spot 180 sx Class H Cement plug from 1015'-765'.
7. Spot 100 sx Cement plug from 100'-Surface.
8. Clean location & install dry hole marker.
9. Well P&A 1-7-85.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED W. B. G. L. TITLE Dist. Opr's. Mgr. DATE 1-17-85

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE 6-24-84