

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☒ gas well ☐ other ☐

2. NAME OF OPERATOR

Getty Oil Company 393-7191

3. ADDRESS OF OPERATOR

P. O. Box 728, Hobbs, NM. 88240

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

990' PEL & 1980' FN

AT SURFACE:

AT TOP PROD. INTERVAL:

AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

CHANGE ZONES ☐

ABANDON* ☐

(other) ☐

SUBSEQUENT REPORT OF:

☐
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐
☒

(NOTE: Report results of multiple completion or zone change on Form 9-330)

5. LEASE

LC-032650 (b)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

A.B. Coates "C"

9. WELL NO.

24

10. FIELD OR WILDCAT NAME

Justis Blinbry

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 24, T-25-S, R-37-E

12. COUNTY OR PARISH

13. STATE

14. API NO.

New Mexico

15. ELEVATIONS (SHOW DF, KDB, AND WD)

3081' (DF)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

1. Rigged up. Remove Dual Well Head. Shot 40' to perf west string
2. Set Cement retainer @ 5060' Squeeze Blinbry perfs 5218-5476 (East) Commingle perfs. 5429-5439'. West csg string perfs 5160-5439', Commingle perfs 5160-5170' & East csg string perfs 5175-5000'. W/20 sx class H Cement. Left 50' Cement on top of retainer. CIBP-5175 (East) g1
3. Cut 2 7/8" Csg String @ 1685' & Pull. East
4. Spot 40 sx class H Cement plug from 1774'-1714'. East
5. Spot 120 sx Class H Cement plug from 1747'-1497'. East
6. Spot 180 sx Class H Cement plug from 1015'-165'. Shot
7. Spot 100 sx Cement plug from 100'-Surface.
8. Clean location & install dry hole marker.
9. Well P&A 1-7-85.

Subsurface Safety Valve: Manu. and Type

Set @ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED

[Signature]

TITLE Dist. Opr's. Mgr.

1-17-85

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

RECEIVED

APR - 3 1985

O.S.D.
HABES OFFICE