

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.  
30-025-11720

5. Indicate Type of Lease  
STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name  
SOUTH JUSTIS UNIT "E"

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator  
ARCO Permian

8. Well No.  
22

3. Address of Operator  
P.O. Box 1710, Hobbs, New Mexico 88240

9. Pool name or Wildcat  
JUSTIS BLY TUBB DRKD

4. Well Location  
Unit Letter M : 660 Feet From The S Line and 990 Feet From The W Line  
Section 24 Township 25S Range 37E NMPM LEA County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)  
3079' DF

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ADD PERFS & ACIDIZE ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD: 7000' PBD: 6220' PERFS: 4981-5947'

02/04/97: POH W/2-7/8" TBG. WIH W/BIT, SUB, SCRAPER & 2-7/8" WORKSTRING TO 6024' F.S.  
TESTED TBG TO 5000', POH. WIH W/4" GUNS AND PERF, 1 SPF 4981-5021', 16 HOLES. WIH W/2-3/8"  
SN, BAKER MODEL r PKR, SUBS, 5-1/2" UNLOADER SUB, BAKER SNAPSET PKR, AND 2-7/8" TBG TO 5026'.

02/06/97: SET PKRS @ 5026 & 5042'. PMP 1000 GALS 15% NEFE HCL W/25 BBLS 2% KCL. ACIDIZE  
EXISTING PERFS FROM 5047 TO 5947'. PULLED PKRS UP TO 5008 AND 5024', SET & DROPPED 2-3/8"  
S.V. PMP 800 GALS 15% NEFE HCL W/29 BBLS 2% KCL. ACIDIZE NEW PERFS FROM 4981-5021. FOUND  
SPLIT JOINT @ 1860'.

02/07/97: SET PKRS @ 5008 & 5024'. PMP 1000 GALS 15% NEFE HCL W/29 BBLS 2% KCL. ACIDIZE NEW  
PERFS FROM 4981-5021', POH W/PKRS & WORKSTRING. WIH W/2-7/8" TBG & SET @ 5917'. TESTED &  
LOADED TBG TO 5008'.

~~15% NEFE HCL W/29 BBLS 2% KCL. ACIDIZE NEW PERFS FROM 4981-5021. FOUND  
SPLIT JOINT @ 1860'.~~

~~02/07/97: SET PKRS @ 5008 & 5024'. PMP 1000 GALS 15% NEFE HCL W/2" field Administrative Assistant~~

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

*Kelli D. Murrish*

TITLE

*Admin Asst.*

DATE

*Kelli D. 4-28-97*

TYPE OR PRINT NAME

*Murrish Murrish, Kelli D.*

TELEPHONE NO.

*505-394-1649*

(This space for State Use)

MAY 02 1997

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: