Form 3160-5 (Julie 1990)

## UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

FORM APPROVED Budget Bureau No. 1004-0135

Expires: March 31, 1993

LC 032650B

## SUNDRY NOTICES AND REPORTS ON WELLS

5. Lease Designation and Serial No.

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.	6. If Indian, Alottee or Tribe Name			
Use "APPLICATION FOR PERMIT" for such proposals				
SUBMIT IN TRIPLICATE	7. If Unit or CA, Agreement Designation			
	8. Well Name and Number			
1. Type of Well: OIL SAS OTHER	7			
2. Name of Operator TEXACO EXPLORATION & PRODUCTION INC.	10			
3. Address and Telephone No. P.O. BOX 730, HOBBS, NM 88240 397-0442	9. API Well No. 30 025 11732			
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)	10. Field and Pool, Exploaratory Area Justis Abo			
Unit Letter F: 1980 Feet From The NORTH Line and 2080 Feet From The	Justis Abo			
WEST Line Section 24 Township 25S Range 37E	11. County or Parish, State  LEA , NEW MEXICO			
12. Check Appropriate Box(s) To Indicate Nature of Notice, Re	eport, or Other Data			
	YPE OF ACTION			
TYPE OF SUBMISSION  Abandonment	Change of Plans			
Recompletion	New Construction			
Notice of Intent Plugging Back	Non-Routine Fracturing			
Cosing Popular	Water Shut-Off			
Subsequent Report  Atlering Casing	Conversion to Injection			
Final Abandonment Notice	☐ Dispose Water			
	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log Form.)			
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, in	ncluding estimated date of starting any proposed all markers and zones pertinent to this work,)*.			

- work. If well is directionally drilled, give subsurface locations and measured and true
- 1. RUPU and installed BOP. TOH with production equipment.
- 3. Set CIBP @ 6550' and capped with 35' cement (NEW PBTD @ 6515). Perforated 7'casing with 8sjpf on interval 6220'-6230'. Perforated w/2 JSPF 6250'- 6443'.
- 4. TIH with packer and set @ 6116'.
- 5. Fractured stimulate perforations with 33600 gallons 40# gel + 103400# 20/40 sand. Rate=40 BPM. Max Pres=8000 psi.
- 6. Set packer @ 6333". Acidized perfs 6399' -6443' w/ 6000 gals 15% NE-FE using 113 ball sealers. Max pres=1200 psi, Avg rate=5 BPM.
- 7. Released packer and POH with tubing.
- 8. Cleaned out and TIH with production equipment. Bottom of tubing @ 6454' w/Packer @ 6101'.
- 9. Swabbed well started flowing; placed on test.
- 10. Turned well over to Arco 11-27-95.
  - OPT FLOWING 11-22-95; 0 BOPD, 23 BWPD, 1355 MCFD.

14. I hereby certify that the foregoing is true and correct SIGNATURE	ling	TITLE_	Field Technician	DATE 3/13/96
TYPE OR PRINT NAME	Paul R. Wilcox			
(This space for Federal or State office use)  APPROVED BY		TITLE_		DATE
THE ANY			6th a United State	s any false fictitious or fraudulent statements or
Title 18 U.S.C. Section 1001, makes it a crime f	for any person knowingly and diction.	i willfully to m	ake to any department or agency of the United State	s any raise, notice of the

