

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPPLICATE*
(Other instructions
verse side)

Budget Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

LC-032650-6

8. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

H.B. CONTESE C

9. WELL NO.

15

10. FIELD AND POOL, OR WILDCAT

JUSTIS MONTOYA

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

SEC 24 T25S R37E

12. COUNTY OR PARISH 13. STATE

LEA

NM

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

TEXACO PRODUCING CO.

3. ADDRESS OF OPERATOR

P.O. BOX 728 HOBBS, NM 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)

At surface

660' FSL 1980 FFL SEC 24 T25S R37E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3081 DF

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREAT

MULTIPLE COMPLETION

FRACTURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON*

SHOOTING OR ACIDIZING

ABANDONMENT*

REPAIR WELL

CHANGE PLANS

(Other)

(Other)

(Note: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

- ① PULL PRODUCTION EQUIPMENT, TTH WITH RTT, UC'S, ON 2 7/8 WS CLEAN OUT TO FEEL GRIE, TCH
- ② RUN GR-CCL CORRELATION LOG FROM 5900' TO 6900', PERF ADDITIONAL MONTOYA PAY 6803-07, 6817-21, 6826-32, 6835-37, 6844-48 2 SEIF, 40 HOLS
- ③ TTH w/ RBP, PKR ON 2 7/8 WS SET RBP @ 6856' SET PKR @ 6720'
- ④ ACIDIZE PERFS 6803-48 w/ 2000 GALS 15% HFF ACID USING 100% EXCES BALL STALLS TO LIFT
- ⑤ RELEASE PKR, RETRIEVE RBP, TCH
- ⑥ TTH w/ PRODUCTION EQUIPMENT, PLACE WFL ON PRODUCTION

18. I hereby certify that the foregoing is true and correct

SIGNED

[Signature]

TITLE

AREA SUPERINTENDENT

DATE

SEP 11 1987

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

9 29 87

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side