Form 3160-5 (June 1990)

or representations as to any matter within its jurisdiction.

UNITED STATES DEPARTMENT OF THE INTERIOR HOBBS. NEW BUREAU OF LAND MANAGEMENT

FORM APPROVED Budget Bureau No. 1004-0135

Expires: March 31, 1993


5. Lease Designation and Serial No. LC-032650B


SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.

6. If Indian, Allottee or Tribe Name

CHOM	R PERMIT—" for such proposals	
SUBMIT IN TRIPLICATE		7. If Unit or CA, Agreement Designation
1. Type of Well Oil Well Well Other		
2. Name of Operator Texaco Exploration and Production Inc. AS AGENT FOR ARCO OIL & GAS		8. Well Name and No. A.B. COATES C FED #12
3. Address and Telephone No.	IIC. AS ABEDI FOR MECO DIL & GAS	9. API Well No.
P.O. Box 730, Hobbs, NM 88240	505-393-7191	30-025-11734
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)		10. Field and Pool, or Exploratory Area
	comptions	Justis Fusselman
1980'FSL & 1650' FWL Unit K, Sec 24, T-25-S, R-37-E		11. County or Parish, State Lea
CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPOR	
TYPE OF SUBMISSION	TYPE OF ACTION	, on other bath
Notice of Intent	Abandonment	
	Recompletion	Change of Plans
Subsequent Report	X Plugging Back	New Construction
	Casing Repair	Non-Routine Fracturing
Final Abandonment Notice	Altering Casing	Water Shut-Off
	Other Abandon Fusselman zone	Conversion to Injection
		Dispose Water (Note: Report results of multiple completion on W Completion or Recompletion Report and Log form
release packer, pressure from surface (Chart to NMOCD, copy on reverse : Drill cmt & CIBP, push junk to 5590'.	on top, set packer @ 2064', pressure down tule to 5600' to 580# 30 min - Held OK.	bing to 600# held OK
Potume well to another		omy to coom, mad on.
Return well to production, turn over to		omg to coom, mad dic.
Return well to production, turn over to		70 -
Return well to production, turn over to		Jun 2
Return well to production, turn over to		Jun 21
Return well to production, turn over to	ARCO.	Jul 21 1
Return well to production, turn over to		Jun 21 II
Return well to production, turn over to	ARCO.	Jul 21 II 43
Return well to production, turn over to	ARCO.	Jun 21 II
Return well to production, turn over to	ARCO.	RECEIVED Jul 21 II 43 M
Return well to production, turn over to	ARCO.	HECEIVE Jul 21 11 43 / CAP ARES
Return well to production, turn over to	ARCO.	MEGEIVED ARES ARES ARES ARES ARES ARES ARES ARES
Return well to production, turn over to RE: R-9745, well renamed South Justis I hereby certify that the foregoing is true and correct	o ARCO. Unit F #22 operated by ARCO OIL & GAS.	RECEIVED Jul 21 II 43 M
RE: R-9745, well renamed South Justis Thereby certify that the foregoing is true and correct Signed	o ARCO. Unit F #22 operated by ARCO OIL & GAS.	Jun 21 II va MY 93
Return well to production, turn over to	ARCO.	Jun 21 II 43 /





JUN 1 5 1993

CCD HOBBS OFFICE