5 - USGS (Lea County) 1 - CK (Foreman) 1 - Admin. Unit (Midlane Form Approved. 1 - File Budget Bureau No. 42-R1424 Form 9-331 Dec. 1973 UNITED STATES 5. LEASE DEPARTMENT OF THE INTERIOR LC-032650 (b)_ 6. IF INDIAN, ALLOTTEE OR TRIBE NAME GEOLOGICAL SURVEY 7. UNIT AGREEMENT NAME SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.) 8. FARM OR LEASE NAME נוט A. B. Coates "C" gas Dual 9. WELL NO. other well well 12 2. NAME OF OPERATOR 10. FIELD OR WILDCAT NAME Getty Oil Company Justis Fusselman & Tubb Drinkard U.S. A 3. ADDRESS OF OPERATOR 11. SEC., T., R., M., OR BLK. AND SURVEY OR P. O. Box 730 Hobbs, New Mexico. AREA 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 Section 24, T-25S, R-37E 1980 FSL - 1650 FWL below.) 12. COUNTY OR PARISH 13. STATE AT SURFACE: NMAT TOP PROD. INTERVAL: 14. API NO. AT TOTAL DEPTH: 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, 15. ELEVATIONS (SHOW DF, KDB, AND WD) REPORT, OR OTHER DATA 3084 DF SUBSEQUENT REPORT OF: REQUEST FOR APPROVAL TO: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE (NOTE: Report results of multiple completion or zone REPAIR WELL change on Form 9-330.) PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other) Repair packer/ tubing leak & acidize 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* The subject well is temporarily shut-in due to either packer leakage or tubing leak Rig up pulling unit and install BOP. 1. Pull both strings of sucker rods. 2. Run Dialog to determine condition of tubing. 3. Pull short string then long string with parallel string anchor. 4. Hydrotest long string back in hole. 5. Acidize Justis Fusselman with 3200 gallons 15% NE HCl acid. Hydrotest short string back in hole. 7. Acidize Justis Blinebry with 5000 gallons 15% NE HCl acid. _. _ Set @ Ft. Subsurface Safety Valve: Manu, and Type 18. I hereby çertify that the foregoing is true and correct Area Superintendent August 4, 1981 SIGNED APPROVEUThis spage for Federal or State office use APPROLED BY (Orig. Sgd.) PETER W. CHESTER E PATE PPROVAL, IF ANY CONSIDER OF AUG 1 0 1901

FOR

JAMES A. GILLHAM

DISTRICT SUPERVISOR See I structions on meverse Side