

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPLI  
(Other instructions  
verse side)

Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

**LC-032650 (b)**

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

**A. B. COATES "C"**

9. WELL NO.

**21**

10. FIELD AND POOL, OR WILDCAT

**JUSTIS BLINEBRY**

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

**24-25S-37E**

12. COUNTY OR PARISH

**LEA**

13. STATE

**NEW MEXICO**

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR  
**GETTY OIL COMPANY**

3. ADDRESS OF OPERATOR  
**P.O. BOX 249, HORRS, NEW MEXICO 88240**

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface

**2080' FSL & 1980' FSL**

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

**3084 D.F.**

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON\* ☐

CHANGE PLANS ☐

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

SUBSEQUENT REPORT OF:

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT\* ☒

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Well previously completed in the Blinebry-Mc Kee - Montoya Zones. Plugged off Montoya and Mc Kee Zones and completed as a single Blinebry producer as follows:

Pulled all three tubing strings. Ran DR Plug on tubing and set in Model "D" Packer @ 7150'. Ran dump bailer and dumped 10' cement on top of plug.

Set CIBP @ 6787'. Dumped 10' cement on top of BP. PSTD @ 6777'. Ran 2-3/8" tubing with TIW Packer and Hydraulic Holddown. Set tubing @ 5255', packer @ 5245'. Tubing tested above slips @ 4500#. Swabbed Blinebry down to 5100'. 12 hr. SITP 50#, FL 4200'.

Acidized Blinebry with 1,000 gal. 15% NE FE stabilized acid, in on vacuum. Swabbed back load. Released TIW packer and left swinging. Ran rods and pump.

18. I hereby certify that the foregoing is true and correct

ORIGINAL SIGNED BY:

SIGNED C. L. Wade

TITLE AREA SUPERINTENDENT

DATE November 17, 1971

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

TITLE \_\_\_\_\_

DATE 20

1971

\*See Instructions on Reverse Side

## Instructions

**General:** This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

**Item 4:** If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

**Item 17:** Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

U.S. GOVERNMENT PRINTING OFFICE: 1963 O-685229

847 - 485

RECEIVED  
201071  
FEDERAL BUREAU OF INVESTIGATION  
WASHINGTON, D.C.