Form 3160-5 11 December 1989; RECEIVED UN DEFORTME		estate and the second
		FORM APPROVED Budget Bureas No. 1004-0135
17 11 10 RUREAU OF LAND MANAGEMENT		Expires: September 30, 1990 5. Lease Designation and Serial No.
Do not use this form for prophets AND REPORTS ON WELLS		I C COOCEO CO
	PANU REPORTS ON-WELLS drill or to deepen or reentry to a different reservoir. DR PERMIT—" for such proposals	6. If Indian, Allottes or Tribe Name
I. Type of Well	SUBMIT IN TRIPLICATE	
X Oil Gas Other		S. Well Name and No.
•	Toyago Dunda /	
Texaco Producing Inc. 3. Address and Telephone No.		A. B. Coates C. #22 9. API Well No. 39-025-11744
P.O. Box 730, Hobbs, NM 8	P.O. Box 730, Hobbs, NM 88240 (505) 393-7191 4. Location of Well (Footage, Sec., T., R., M., or Survey Description)	
Unit B, 660 FNL & 2310 FEL		10. Field and Pool, or Exploratory Area Instig (Superin) Montage 11. County or Parish, State
•	Sec 24, T-25-S, R-37-E	
12. CHECK APPROPRIATE BOX	(S) TO INDICATE NATURE OF MOTION	Lea Co, N.M.
TYPE OF SUBMISSION	Lea Co, N.M. X(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	
Notice of Intent	TYPE OF ACTION	
Subsequent Report	Abandonment	Change of Plans
Superform Report	Plugging Back	New Construction Non-Routine Fracturing
Final Abandonment Notice	Casing Repair	Water Shut-Off
		rkover
13. Describe Proposed or Completed Operations (Clearly steel)	(Note: Report results of Recompletion Report an i pertinent details, and give pertinent dates, including estimated date of starting all depths for all markers and zones pertinent to this work.)*	multiple completion on Well Completion or
(1) MIRU, install BOP, pull ro (2) GIH with bit, 7" casing so	ds and pump, TOH tubing.	
(4) Sat made and check for cas	os and pump, TOH tubing. raper and bulldog bailer. Clean hole a ing restrictions. GIH with 7" packer of 6625'.	nd analyze scale.
(2) ACIDIZE with 2000 calcules	17	
(6) Flush perfs with 40 Phis	NeFe in two stages with rock salt blo roduced water. Pump 2 drums scale inhi ed water. Shut in 48 hours.	cks.
POLIS WILL 40 BOIS P	ruip 2 uruis scale inhi	bitor using salt blocks
(7) Flush with 200 Bbls produce	ed water. Shut in 48 hours.	Sait Diocks.
(7) Flush with 200 Bbls production (8) Pull packer. Run production	ed water. Shut in 48 hours. n equipment.	Said blocks.
(7) Flush with 200 Bbls produce	ed water. Shut in 48 hours. n equipment.	Saic Mocks.
(7) Flush with 200 Bbls produce	ed water. Shut in 48 hours. n equipment.	Saic Diocks.
(7) Flush with 200 Bbls produce	ed water. Shut in 48 hours. n equipment.	Said Diocks.
(7) Flush with 200 Bbls production (8) Pull packer. Run production	ed water. Shut in 48 hours. n equipment.	Said Diocks.
(7) Flush with 200 Bbls production (8) Pull packer. Run production 14. I hereby cerufy that the foregoing is true and correct Signed 13.	n equipment.	
(8) Pull packer. Run production 14. I hereby certify that the foregoing is true and correct Signol. (This space for Federal or State office use)	ed water. Shut in 48 hours. n equipment. Title Engr.Asst.	Date
(7) Flush with 200 Bbls production (8) Pull packer. Run production 14. I hereby cerufy that the foregoing is true and correct Signed 13.	n equipment.	
(7) Flush with 200 Bbls production (8) Pull packer. Run production 14. I hereby cerufy that the foregoing is true and correct Signed. (This space for Federal or State office use) Approved by Conditions of approval, if any:	n equipment. Title Engr.Asst. Title	Date 12-10-90 Date 12-24-90
(7) Flush with 200 Bbls production (8) Pull packer. Run production 14. I hereby cerufy that the foregoing is true and correct Signed. (This space for Federal or State office use) Approved by Conditions of approval, if any:	n equipment. TitleEngr.Asst.	Date 12-10-40 Date 12-24-90

Provide the

DEC 3 1 1990

HOSS OFFIS