

5-0503
1-R.L. WHITE - MIDLAND
Form 9-331
(May 1963)

1-FILE

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPL
(Other instructions
verse side)

E*
re-

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC-032650 (b)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

A. B. COATES "C"

9. WELL NO.

22

10. FIELD AND POOL, OR WILDCAT

JUSTIS BLBY-T. DRK.

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

24-25S-37E

12. COUNTY OR PARISH

LEA

13. STATE

N.M.

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR
GETTY OIL COMPANY

3. ADDRESS OF OPERATOR
P.O. BOX 249, HOBBS, NEW MEXICO 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

660' FNL & 2310' FEL, section 24

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3080 D.F.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) MULTIPLE COMPLETE ☒

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Perforated Tubb Drinkard @ 5638, 40, 50, 52, 54, 56, 68, 70, 72, 88, 90, 92, 94, 96, 98, 5700, 02, 04, 06, 08, 10, 40, 42, 44, 74, 76, 96, 5802, 5814, and 16' with one 3/8" shot at each interval and treated above perforations with 5,000 gals. 15% J HCL acid, using 45 ball sealers. Swabbed - Tubb Drinkard Zone unproductive. Set CIBP @ 5625' and dumped 35' cement on BP. PHTD 5590'. Ran tubing, rods and pump to produce Blinebry.

18. I hereby certify that the foregoing is true and correct

ORIGINAL SIGNED BY:

SIGNED C. L. Wade

C. L. Wade

TITLE AREA SUPERINTENDENT

DATE 12-21-76

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

ACCEPTED FOR RECORD
DATE

DEC 23 1976

U. S. GEOLOGICAL SURVEY
HOBBS, NEW MEXICO

WLG/bh

*See Instructions on Reverse Side