

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO

3002511748

5. Indicate Type of Lease

STATE

FEE

6. State Oil / Gas Lease No.

LC032650A

7. Lease Name or Unit Agreement Name

COATES, A. B. -D-

8. Well No.

3

9. Pool Name or Wildcat

JUSTIS-FUSSELMAN

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT
(FORM C-101) FOR SUCH PROPOSALS.

1. Type of Well.

OIL
WELL



GAS
WELL

OTHER

2. Name of Operator

TEXACO EXPLORATION & PRODUCTION INC.

3. Address of Operator

205 E. Bender, HOBBS, NM 88240

4. Well Location

Unit Letter

N

990

Feet From The

SOUTH

Line and 2310

Feet From The

WEST

Line

Section 24

Township 25S

Range 37E

NMPM

LEA COUNTY

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3085 DF

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK

PLUG AND ABANDON

REMEDIAL WORK

ALTERING CASING

TEMPORARILY ABANDON

CHANGE PLANS

COMMENCE DRILLING OPERATION

PLUG AND ABANDONMENT

PULL OR ALTER CASING

CASING TEST AND CEMENT JOB

OTHER:

OTHER:

SET CIBP & ADD PERFS

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3-20-01: MIRU KEY. NDWH. NUBOP. TIH W/BIT & CSG SCRAPER TO 1900'.

3-21-01: KILL W/30 BBLs 2% KCL WTR. TIH W/BIT & SCRAPER ON TBG. TAG @ 6850. RUN GR/CCL FR 6800-5500. TIH W/CIBP & SET @ 6760. TIH W/PERF GUN & PERF FUSSELMAN FR 6632-36,6647-56,6658-62,6666-72,6678-82,6718-20. TIH W/TBG TO 2000.

3-22-01: KILL W/40 BBLs 2% KCL WTR. TIH W/PKR, & SN ON TBG & TEST TO 5000#. SET PKR @ 6541'. LOAD & TEST BACKSIDE TO 400#. UNSET PKR & PULL TO 6411. TIH W/SONIC HAMMER TOOL ON TBG TO 6607'.

3-23-01: ACID WASH PERFS 6632-6741 W/3000 GALS 15% NEFE HCL. RU SWAB. FL @ 3500. END FL @ 3900.

3-26-01: TIH W/SMJ W/PURGE VALVE, SN, TBG, & TAC ON 2 7/8" TBG. NDBOP. ATTEMPT TO SET TAC 6598,6467,6336,5302. WOULD NOT SET. LEFT SWINGING @ 5302.

3-27-01: TIH W/TAC. MA @ 6732. SN @ 6704. TAC @ 6546. NDBOP. NUWH. TIH /GAS ANCHOR. PUMP, SNKR BARS, & RDS. HUNG ON & LOAD & TEST TO 500#. OK.

3-28-01: NDWH. UNSET PUMP & BACK OFF RDS. PUMPING @ 12:30 PM. RIG DOWN.

4-04-01: ON 24 HR OPT. PUMPING 9 BO,532 BW, & 109 MCF.

FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

J. Denise Leake

TITLE

Engineering Assistant

DATE 5/31/01

TYPE OR PRINT NAME

J. Denise Leake

Telephone No. 397-0405

(This space for State Use)

APPROVED

CONDITIONS OF APPROVAL IF ANY:

TITLE

DATE