

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION
 Orig&2cc: OCC, Hobbs
 cc: Regional Office
 cc: file

HOBBS, N.M., U.S.A.

MAY 15 7 57 PM '67

Form C-103
 Supersedes Old
 C-102 and C-103
 Effective 1-1-65

5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.
7. Unit Agreement Name
8. Farm or Lease Name Wimberly WN
9. Well No. 4
10. Field and Pool, or Wildcat Justis Tubb Drinkard Justis Fusselman
12. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
 USE "APPLICATION FOR PERMIT - 1" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>
2. Name of Operator Sinclair Oil & Gas Company
3. Address of Operator P. O. Box 1920, Hobbs, New Mexico
4. Location of Well UNIT LETTER <u>E</u> , <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>990</u> FEET FROM THE <u>West</u> LINE, SECTION <u>24</u> TOWNSHIP <u>25S</u> RANGE <u>37E</u> NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 3084' DF

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
 NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input checked="" type="checkbox"/> Temporarily Abandon	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/> Justis Tubb Dri.	OTHER <input type="checkbox"/>

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	
OTHER <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD 7242', PBTD6805' Completed in Justis Tubb Dri. 5890-5920' and Justis Fusselman 6754-6794'.

PROPOSE TO: Run tubing to Model D Packer @ 6670', to test packer. Run 5"OD scab liner and set approx. 5852'-5962' w/Brown Oil Tools packer @ bottom and top to blank off Dri. perforations 5890-5920'. Test liner and casing, if ok, complete as single completion in Justis Fusselman perms. 6754-6794'.

*Wimberly About
Perms @ 6840'
6950' 77*

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Superintendent DATE 5-12-67

APPROVED BY _____
 CONDITIONS OF APPROVAL, IF ANY:

ORIGINAL
 SIGNED BY
 ENGINEER

DATE