

Form 316C-5
(July 1989)
(Formerly 9-331)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

CONTACT RECEIVING
OFFICE FOR NUMBER
OF COPIES REQUIRED
(Other instructions on reverse
side)

BLM Roswell District
Modified Form No.
NMO60-3160-4

5. LEASE DESIGNATION AND SERIAL NO.
NM-0766

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT-" for such proposals.)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

7. UNIT AGREEMENT NAME

2. NAME OF OPERATOR
MERIDIAN OIL INC.

8. FARM OR LEASE NAME
CARLSON "A"

3. ADDRESS OF OPERATOR
P.O. Box 51810, Midland, TX 79710-1810

3a. AREA CODE & PHONE NO.
915-688-6906

9. WELL NO.
1

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface
J, 2310' FSL & 2310' FEL

10. FIELD AND POOL, OR WILDCAT
JUSTIS (BLINEBRY) Tubbs Drinkard

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA **R 9745**
11/1/92

SEC. 25, T-25-S, R-37-E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
3065' GR

12. COUNTY OR PARISH
LEA

13. STATE
NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other)

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) **REQUEST TA STATUS**

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐

X

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

BEFORE WORKOVER: TD 6954', RBP @ 5121', PKR @ 6200' W/EXPENDABLE PLUG IN PKR.

WORKOVER : SQZD TUBB-DRINKARD PERFS 5732'-5940'. SQZD BLINEBRY PERFS 5253'-5395'. CSG COLLAPSED @ 5293'. SET CIBP @ 5000'. RAN CSG INTEGRITY TEST. WELL TA'D.

12-12-91 TAGGED JUNK @ 5252'.

12-13-91 RIH W/IMPRESSION BLOCK.

12-14-91 IMPRESSION BLOCK INDICATED TBG HAD BEEN CUT OR PULLED INTO. FISHING.

12-15 THRU 19-91 FISHING. REC'D JUNK. RAN BIT & SCRAPER TO 6148'.

12-20-91 SET PKR @ 6148' & TEST TO 1500 PSI FOR 15 MINS., OK. SET PKR @ 5600', PRESS'D TO 500 500 PSI, BLED TO 0 PSI IN 3 MIN. EST INJ RATE INTO TUBB-DRINKARD PERFS 5732'-5940'. SET CMT @ 5690'.
RTN

12-21-91 STINGED INTO RET @ 5690', PUMPED 50 SXS C CMT W/.3 GPS D-604 + 60 SXS C NEAT CMT. LOST ALL PRESS. SET CMT RET @ 5164', SQZD BLINEBRY PERFS 5253'-5395' W/150 SXS RFC 12-2A CMT + 200 SXS H CMT W/.8% D-127 + 1% CACL2.

18. I hereby certify that the foregoing is true and correct

SIGNED

Nancy L. Perry

TITLE

PRODUCTION ASST.

DATE

1-30-92

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

2/24/92

APPROVED FOR **12** MONTH PERIOD

ENDING **12/30/92**

*See Instructions on Reverse Side

12-22 thru 23-91 DRLD OUT RET & CMT TO 5208', GREEN CMT,
WOC.

12-24-91 DRLD OUT CMT TO 5268'. PRESS'D CSG TO 500#,
BLED TO 0 PSI IN 10 MINS.

12-25-91 SET CMT RET @ 5007'. PRESS'D ANNULUS TO 500
PSI, HELD GOOD.

12-27-91 PUMPED BELOW RET @ 5007' W/100 SXS C CMT W/
.7% D-127, TAILED W/100 SXS C CMT W/1%
CACL2. WOC.

12-28-91 DRLD OUT RET & CMT TO 5080', GREEN CMT,
WOC.

12-29 THRU 30-91 DRLD OUT CMT TO 5293'. BIT TORQUEING &
JUMPING.

12-31-91 RAN IMPRESSION BLOCK, INDICATED COLLAPSED
CSG @ 5293'. SET CIBP @ 5000', TEST TO 500
PSI, OK. CIRC'D HOLE W/PKR FLUID.

CASING INTEGRITY TEST CHART ATTACHED. REQUEST APPROVAL FOR
TEMPORARILY ABANDONED STATUS.

